

KTGI

Tangier Island
Tangier, VA

1.00 mi W of city N37 49.5519' W75 59.8598' Mag Var: 11W

Nav aids:	Type:	ID:	Morse:	Frequency:	Radial:	Distance:
	VORTAC	CCV	— · — · — · —	112.2	370	29 nm
	VORTAC	SWL	·· — — —	112.4	249	29 nm
	VORTAC	SBY	·· —·· — —	111.2	229	39 nm

Traffic Patterns (FAA):
TPA Lgt Acft 600' Hvy Acft 1500'
Right: 02 Left: 20

Runways:
Name: **Dimensions:** **Material:** **Condition:** **Treatment:**
02/20 2426X75 asphalt fair no treatment
Tree; 380' from end; 56' Left of center; 7' high; 25:1 clearance slope;
Road; 249' from end; 0' Both-Sides of center; 15' high; 3:1 clearance slope;

Lighting:
Airport Bcn Out of service Indefly.

Charts: NACO: Washington Sectional

Phone: 757-891-2496

Weather: 757-891-2246 (AWOS-3)

Clearance Delivery Phone: 301-342-3740; When Approach Closed: 866-640-4124;

Communication Freqs:
127.2 App(S) Dep(S)
 (WHEN NHK APCH CLSD)
121.0 App/Dep
119.8 WX
 CD (When Approach Closed)
122.8 CTAF
122.8 UNICOM

Elevation: 5 ft (1.5 m)



Notes:
Apr-Oct/Sat-Sun/0800-1630
Be Alert: Rstd Area One Mi West of Arpt; Hi-Speed Acft Drop Bombs & Fire Live Ammunition in Area.
For Clearance Delivery Contact Patuxent Approach at 301-342-3740, When Patuxent Approach is Clsd CTC Potomac Approach at 866-640-4124.
Landing/Parking Fee to Help Pay for Recent Rwy Rehab.
Paew Adjacent to All Rwys, Twys & Ramps.
Town Office (757) 891-2438.
Prev Rwy Nrs Vsb on Former Rwy Pavement. Chevrons on Former Rwy Pavement Poor.
Rwy Centerline Poor.
Twy Lead-In Lines Poor. Rwy Centerline Poor.

