

W55

Kenmore Air
Seattle, WA

1.00 mi N of city N47 37.7392' W122 20.3243' Mag Var: 20E

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOT	BFI	108.6	347	6 nm
VOT	SEA	117.5	352	11 nm
VORTAC	SEA	116.8	335	12 nm

Traffic Patterns:
No TPA reported. Assume 1,000 AGL.
Left: 16W,34W

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
16W/34W	5000X500	water	not reported	no treatment

Communication Freqs:
122.9 CTAF

Noise Abatements:

RnWy:	Arcrft:	App/Dep:	Noise Abatement:
All	All	Both	No dep bfo 7:30 am wkdays, 8:30 am Sat, 9 am Sun & hol

Charts: NACO: Seattle Sectional

Phone: 425-486-1257

Clearance Delivery Phone: 206-214-4722;

Other (Non-FBO) Businesses Summary:

Kenmore Air Harbor, LLC.


Location: NE

Phone: 425-486-1257; Hours: 01/01-12/31, Sun-Sat, 08:00-17:00;

Elevation: 14 ft (4.3 m)

No Diagram Published

Generated 5/20/2025 at
<http://www.aopa.org/destinations/airports/W55/details>
Copyright 2025 Aircraft Owners and Pilots Association



Notes:
Year-round, 7 Days a Week,Dawn-Dusk
All Takeoffs & Landings in Center of Lake.
Apch Surface Data not Checked.
Call 425-486-1257 X2010 for Apvl At Least 3 Hrs Prior to Arr. Docking Fee.
Do not Taxi Closer Than 200 Ft Fm Shoreline Excp in Close Proximity to Kenmore Air Harbor.
Five Tempo Buoys Have Been Placed Along the North-South Cntrln of Lake Union, Each Separated by Approximately 750Ft, and Mark the Aprx Location of the Preferred Seaplane Opr Area. the Buoys Have A Yellow Flashing Light That Can be Actvt by Five Clicks on 122.9, to Alert Boaters of an Impending Seaplane Tkof or Landing. Run Time on the Lights is 60 Seconds. the Buoy/Light System is Advisory Only, and Boaters are not Required to Clear the Area. the Buoys Will be Removed Within Five Days Following Labor Day, or Earlier.
For Clearance Delivery Contact Seattle Approach at 206-214-4722.
Fuel Avbl Emerg Only.
Incrd Boating Operations on Lake May 15 Thru Sep 15.
Kenmore Air Lake Union Dock Freq 130.30.
Kite Flying in Public Park At N End of Airport and Uavs Operating At the N and S Ends.
Night Landings not Recommended Due to Unlighted Small Watercraft.
Special Noise Abatement Rules in Effect Contact Operator for Pattern Information.
When Consistent with Safety, Avoid 'On the Step' Operations South and West of Red Buoy. Extn 2240.
Owners: Green Hornet Enterprises LLC and Munro Banks Holdco Inc.
\$150 Transit Docking Fee.
Airport Has Scheduled Airline Service