KBAB

Beale Afb
Marysville, CA

6.00 mi E of city N39 8.1660' W121 26.1952' Mag Var: 16E

Navaids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOR/DME	MYV	__ _.__ ..._	110.8	054	7 nm
VOT	SMF	... __ .._.	111.4	015	28 nm
VORTAC	ILA	.. ._.. ._	114.4	064	28 nm

Traffic Patterns (FAA):

Tfc Pat: Rectangular Pat 1100'
Ovhd Pat 2100'
Ftr Type Acft Fly Rp Rwy 15
Left: 15 (Assumed Left: 33)

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
15/33	12001X300	concrete	not reported	grooved

Tower:

Tower Hrs: OPR H24 FR 1400Z++ MON THRU 0600Z++ SAT, AND/OR BY NOTAM; CLSD WKEND AND HOL.
Ptd-141.1 For Use Only Within 16.2 Nm, 15,000 Ft Or Blw.
Radar - Par - No Notam Mp: 1500-1730Z++ Mon-Fri.
Wing Comd Post - 321.0 311.0 (321.0 Inbd Acft Ctc Comd Post 35 Min Prior Eta With Intentions.)

Charts: NACO: San Francisco Sectional

Phone: 530-634-4823

Other (Non-FBO) Businesses Summary:

Beale Aero Club & Flight Training Center
Phone: 530-634-9011; Hours: 01/01-12/31, Mon-Sun, 10:00-16:00;

Elevation: 113 ft (34.4 m)



Notes:

RESTRICTED. MILITARY AIRPORT. PRIOR PERMISSION REQUIRED. CONTACT BASE OPS MANAGER 530/634-2002
All
Afrc: 940Th Comd Post, Dsn 368-1960, C530-634-1960.
Atis: Opr When Aerodrome is Open.
Bearing Strength Rwy 15/33: S160 T300 St175 St175 Sbtt620 Tt490 Tdt840.
Bearing Strength Rwy 15/33: S81, T122, St175, Sbtt590, Tt490, Tdt840.
Caution: Beale Air Force Base is Lctd on A Maj Migratory Bird Flyway.
Caution: Use Extreme Caution for Unmanned Acft Act in Vcnty of Beale Afb.
Cstms/Ag/Img: 24 Hr Pn Rqr for Cstms and Ag.
Cstms/Ag/Img: Ltd Cstms/Ag Avbl to Mil Acft Only, 24 Hr Pn Rqr. CTC Airfield Mgt At C530-634-2002 or Dsn 368-2002.
Fluid: W Sp Lpox Lox.
For Cd When Air Traffic Control Tower is Clsd CTC Norcal Approach at 916-361-6874
Fuel: J8.
Jasu: (Am32A-60A) (A/M32A-86) 7(Mc-1A) (Mc-2A).
Misc: for Support Outside of Airfield Opr Hrs (I.E., Wkends, Wing Down Days and Hol) CTC Beale 9Rw Command Post, Dsn 368-5700, C530-634-5700.
Misc: No Space-A Pax Support Avbl on Wkends, Hol, and Acc Family Days.
Misc: Storage of Classified Mtrl Unavbl At Airfield Mgmt; CTC Command Post Dsn 368-5700, C530-634-5700, H24 Prior.
Misc: Tran Acft Exp Progressive Taxi. No Comsec Material Avbl. Tran Aircrew Should Plan to Arr with Appropriate Comsec to Complete Entire Msn. Rwy 15-33 Grooved. Class C Airspace Cont.
Misc: Wx Svc Avbl H24. Current Wx Obsn Avbl Via Atis or CTC Atc.
Oil: O-128-133-148.
Pmsv Metro: Wx Obsn Avbl H24 Via Auto Obsn Sys; Wx Svc Avbl 1 Hr Prior to Airfield Opr Hrs and Dur Fcst Severe Wx Dsn 368-9134, C530-634-9134. Dur Wx Flt Closures Remote Briefing Svc Avbl from 25 Op Wx Sq Dsn 228-6598/6599/6588.
Pmsv Metro: When Auto Obsn Sys Inop, Obst Fr 325-060 Deg, 080-220 Deg, and 245-280 Deg May Impact Prevailing Vis.
Rstd: No Unannounced Acft Practice Apch. Inbound Tsnt Acft Obtain Apvl from Ctl Twr Dsn 368-9140 for Acft Practice Approach Prior to Flt. Ltd Prkg Avbl.
Rstd: Prior Permission Required 24 Hr Pn, CTC Base Operations Dsn 368-2002/9120, C530-634-2002/9120. Issued Prior Permission Required Valid 1 Hr +/- Eta, Early/Late Arr/Dep Must Re-Coord.
Rstd: Vip Prkg Rstd to Acft with Wingspan 85 Ft or Less. Lrgr Dv Acft Will Park on Cargo Spots.
Rwy Lgts: Ry 15, Sf.
Rwylgts: Ry 33, Sf.
Svc Tran Alert: Lav Cart Avbl for Tsnt Acft with Prior Cdn. Aircrew Will Have to Perform Their Own Lav Svc and Cleanup.
Svc Tran Alert: No Potable Water or Ice Svc.
Tran Alert: Svc Avbl 1500-0600Z++ Mon-Fri Exc Federal Hol. Acft That Arr After 0600Z++ Will not be Svcd Until Next Duty Day. Fleet Svc Avbl, 24 Hr Pn.
Rwy 300 Ft Wide Marked At 200 Ft; Full 300 Ft Width Usbl.

Generated 5/18/2025 at
http://www.aopa.org/destinations/airports/KBAB/details
Copyright 2025 Aircraft Owners and Pilots Association