7N8

Butter Valley Golf Port Bally, PA

1.00 mi E of city N40 23.8463' W75 33.7913' Mag Var: 11W

Navaids:

Distance: Type: ID: Morse: Frequency: Radial: VÖRTAC PTW 116.5 368 11 nm VOR/DME ETX 110.2 162 12 nm 204 20 nm VORTAC FJC 117.5

Traffic Patterns (Airport Manager):

Aircraft: Altitude (MSL):

Light Aircraft 1300

Left: 16,34

Runways:

Name: Dimensions: Material: Condition: Treatment: no treatment

Tree; 14' from end; 80' Left of center; 24' high; 0:1 clearance slope;

Road; 0' from end; 10' high; 0:1 clearance slope;

Communication Freqs:

122.9 CTAF CD

Charts: NACO: New York Sectional

Phone: 610-845-2491

Clearance Delivery Phone: 800-728-6322;

Notes:

Year-round, 7 Days a Week, Daylight

For Clearance Delivery Contact Allentown Approach at 800-728-6322.

Rwy 16/34 Lctd in Middle of Golf Course.

Rwy 34 119 Ft Tree Line 1472 Ft Fm Rwy End; 233 Ft Right. 12:1 Slope to Dthr.

Trees & Substantial Trrn Elev Chgs Within 125 Ft of Each Rwy Edge. Rwy 16/34 1535 Ft X 24 Ft Asph Insert At S End; Remainder Turf.

Cting Obstn Exceeds A 45 Deg Slp.

Dsplcd Thld Mkd by 3 Yellow Tires.

Marked with Yellow Wood Panels; Turf Rwy Edges Marked with Tires Painted Yellow.

Apch Ratio 25:1 to 250 Ft Dsplcd Thld.

Displicd Thid Mkd by 3 White Lines.

Elevation: 500 ft (152.4 m)

No Diagram Published



Copyright 2025 Aircraft Owners and Pilots Association