

KASE

Aspen-Pitkin County/Sardy Fld Aspen, CO

3.00 mi NW of city N39 13.3127' W106 52.0940' Mag Var: 09E

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOR/DME	DBL	..- -... -..	113.0	163	13 nm
VOR/DME	SXW	... -.. -..	109.2	155	25 nm
VOR/DME	RIL	..- .. -..	113.35	105	44 nm

Traffic Patterns (FAA):

TPA for Lgt Acft 1185 AGL
TPA for Heavy Acft 1685 AGL
Right: 33 Left: 15

Runways:

Name: **Dimensions:** **Material:** **Condition:** **Treatment:**
15/33 8006X100 asphalt good grooved
Road; 1100' from end; 550' Left of center; 22' high; 40:1 clearance slope;

Lighting:

When Air Traffic Control Tower Clsd Actvt Malsf Rwy 15; REIL Rwy 33; PAPI Rwy 15; MIRL Rwy 15/33 - CTAF. REIL Rwy 15 - Air Traffic Control Tower Ctl, Oper Day VFR Only.
Dusk-2300

Charts: NACO: Denver Sectional

Fees: City/County/Authority, Facility, Landing, Parking, Security

Fuel: 100LL Low-Lead, Jet A1 +Icing Inhibitor


Phone: 970-429-2851

Weather: 970-205-2482 (ASOS)

Communication Freqs:

123.8 *App/Dep*
120.4 *WX*
120.4 *ATIS*
123.75 *Clearance Delivery*
118.85 *CTAF*
121.5 *Emergency*
121.9 *Ground Control*
118.85 *Tower*
122.95 *UNICOM*

Elevation: 7838 ft (2389.0 m)



Tower:

Primary Approach Control Hrs: 0700-2000
Primary Depart. Control Hrs: 0700-2000
Secondary Approach Control Hrs: 2000-0700
Secondary Depart. Control Hrs: 2000-0700
Tower Hrs: 0700-2000
Apch/Dep Ctl Svc Prvdd By Denver Artcc (Zdv) On Freq 128.65/282.2 (Kremmling Rcag - For Mmary Star.
Apch/Dep Ctl Svc Prvdd By Denver Artcc (Zdv) On Freqs 119.85/363.15 (Aspen Rcag)
When Aspen Apch Ctl (Ase) Clsd. Used Also For Harei Star.
Apch/Dep Ctl Svc Prvdd By Denver Artcc (Zdv) On 127.1/343.65 (Montrose Rcag) - For Loyd Star.
Primary Radar Not Avbl. Radar Tfc Advisories & Svcs Avbl For Transponder Equipped Acft Only.

FBO's Summary:

Atlantic Aviation

Location: CTR
Phone: 970-920-2016; Freq: ARINC: 131.025; Hours: 01/01-12/31, Sun-Sat, 06:00-23:00;

Other (Non-FBO) Businesses Summary:

Aspen Aero, LLC

Location: NE
Phone: 970-274-0520; Hours: By Appointment

Aspen Flight Academy

Phone: 970-473-3440; Hours: By Appointment

Fly Aspen

Phone: 970-924-0845; Hours: By Appointment



Notes:

Year-round, 7 Days a Week,0700-2300
(A106) Acft Requiring Ifr Should File Flight Plan with Flight Service 45 Min Prior to Estd Dep.
Airport Clsd 2300-0700.
Airport Located in High Mountain Valley with Mountainous Terrain from 12500 - 14000 Ft MSL in Near Proximity to Arpt; Numerous Unlighted Obstructions. All Adverse Weather Situations Magnified in Mountains. Operations During Periods of Reduced Visibility Discouraged for Pilots Unfamiliar with Area.
Airport Restricted to Maximum Acft Wingspan of 95 Ft.
All Arriving Aircraft Frm 2000 to 2300L Must Announce CTAF 118.85 When They are 20, 15, 10 and 5 Miles Out and on Short Final. Equipment May be on the Rwy.
All Commercial Acft Advise Prior to Pushback Onto Twy-A.
Birds and Other Wildlife on and In vicinity of Rwy. Watch for Wildlife on or Near Rwy
Caution: High Tfc Intxn - Acft Rtnely Hold Short of Twy A4 on Twy A When Inbd to Trml or Ga Ramp.
Cold Temperature Airport. Altitude Correction Required At or Below -21C.
Due to High Approach Mnms Pilots May Need an Ifr Altn Even Though Wx is Fcst to be Higher Than 2000-3.
Due to Poor Visibility in Valley, Use Lndg Lgts in Tfc Pat.
FBO Requires 2 Hrs Advance Notice for Staging Acft Prior to Dep.
For All Ga Operations Btwn 30 Min Aft Ss to 2300 the Following Applies: Acft Equipped As Rqrd Under Far 91.205(D) for Inst Flt - Pilot is Inst Rated; VFR Pic Has Completed At Least One Tkof or Ldng in the Preceding 12 Months At Ase. Ifr: Execute Apch/Dep Procedures with Atc Clnc.
Hang Gliders; Para Gliders; Hot Air Balloon & Glider Operations on & In vicinity of Airport Up to 18000 Ft MSL.
Noise Abatement Procedures in Effect. CTC Airport Operations 970-920-5760 Ext 0.
Pilots are Responsible for Passengers in Ramp Area. Pedestrians and Vehicles Cannot Enter Twys Without Atc Clearance. Stay on the Solid Side of the Red Boundary Marking Line.
Ppr for Tkof on Ry 15. CTC FBO 970-920-2016.
Review of Airplane Performance Rcmdd Including Da; Weight & Balance and Climb Performance.
Terrain Will not Allow for Normal Tfc Patterns. High Rates of Descent May be Rqrd Due to Terrain & Local Procs.
Uncontrolled Traffic on the Ramps. Ry 33 Run-Up Area not Visible from Atct.
Unique VFR Dep Procedures Exist. Call Airport Operations 970-920-5760; or FBO 970-920-2016 for More Info.
Unless Ceilings are At Least 2000 Ft Above Highest Trrn & Vis is 15 Miles or More; Mountain Flying is not Recommended.
Wind Cones Lctd 60 Ft West of Twy A Cntrl.
Rwy Exists to Support the Pkn Lda Assoc with This Arpt.
Pcr Value: 373/F/B/X/T
Papi Unusbl Byd 4 Nm Fm Rwy Thr & Byd 7 Degs Right of Rwy Cntrl.
For Acft Services CTC Unicom.

