| KBLU Blue Canyon - Nyack Emigrant Gap, CA | |
|--|------------------------|
| 1.00 mi S of city N39 16.4983' W120 42.5850' Mag Var: 16E | |
| Navaids: Type: ID: Morse: Frequency: Radial: Distant VOR/DME SWR 113.2 270 21 nm VOR/DME HNW 115.5 346 33 nm VOR/DME MYV 110.8 059 42 nm | n ce: n n |
| Traffic Patterns (Airport Manager):Aircraft:Altitude (MSL):Light Aircraft6284Left: 15,33 | |
| Runways: Dimensions: Material: Condition: Treatment: 15/33 3300X50 asphalt good no treatment Tree; 750' from end; 110' Left of center; 20' high; 27:1 clearance slope; Tree; 400' from end; 0' Both-Sides of center; 15' high; 13:1 clearance slope; | e; |
| Communication Freqs: 120.075 WX 122.9 CTAF | |
| Lighting: Rotg Bcn Out of service Indefly . | |
| Charts: NACO: San Francisco Sectional | |
| Phone: 530-745-3576 | |
| Weather: 530-212-0347 (ASOS) | |
| Clearance Delivery Phone: 510-745-3380; | |
| Notes: Unattended Airport Clsd Ss-Sr. Do not Attempt to Land with Snow on the Runway. No Snow Removal Services an Provided. For Clearance Delivery Contact Oakland ARTCC at 510-745-3380. Located At Dept of Public Works Office, Auburn, Ca. Rwy 15 +4 Ft Brush 100 Ft Fm Thld 125 Ft Left to 125 Ft Right | ıre |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| Elevation: 5 | 284 ft (1610.6 m |
| | |
| Generated 5/28/2025 at | Published |
| Copyright 2025 Aircraft Owners and Pilots Association | |