

KMVL

Morrisville-Stowe State
Morrisville, VT

2.00 mi SW of city N44 32.0613' W72 36.8395' Mag Var: 16W

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOT	BTV	—... — ...	109.0	080	24 nm
VOR/DME	BTV	—... — ...	117.5	086	26 nm
VOR/DME	MPV	— —... —...	116.9	361	28 nm

Traffic Patterns:

No TPA reported. Assume 1,000 AGL.
Left: 01,19

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
01/19	4200X75	asphalt	excellent	no treatment
Power-Line; 2483' from end; 40' Left of center; 93' high; 24:1 clearance slope;				

Lighting:

Actvt REIL Rwy 01 & 19; PAPI Rwy 19; HIRL Rwy 01/19 - CTAF.

Charts: NACO: Montreal Sectional

Fuel: 100LL Low-Lead, Jet A

Phone: 802-279-9746

Weather: 802-888-7934 (ASOS)

Clearance Delivery Phone: 603-879-6859;

Communication Freqs:

135.625 WX
122.8 CTAF
122.8 UNICOM

Elevation: 733 ft (223.4 m)



Notes:

Unattended
3 Ft Swales Mid 1/3 of Rwy on E & W Sides Outside of Rwy Safety Area.
Cold Temperature Airport. Altitude Correction Required At or Below -19C.
For Clearance Delivery Contact Boston ARTCC at 603-879-6859.
Rwy 1 Gldr Operations R Tfc.
Rwy Conds May not be Mnt or Rprtd When Airport is Unattended.

