O22 Columbia Columbia, CA					
	1.00 mi SW of city N38 1.8250'	W120 24.8733	' Mag V	/ar: 16E	
Navaids: Type: VOR/DN VOR/DN VOR/DN	/IE MOD	Frequency: 114.8 114.6 115.5	Radial: 078 030 142	Distance: 28 nm 35 nm 45 nm	
Traffic Patterns (FAA): TPA Rwy 11/29 800' AGL Right: 11,17 Left: 29,35					
Runways: Name:Dimensions:Material:Condition:Treatment:11/292607X50turf, grass, sodgoodno treatmentTrees;2190' from end;125' Left of center;135' high;16:1 clearance slope;Trees;1600' from end;100' Right of center;115' high;13:1 clearance slope;17/354673X75asphaltgoodno treatmentTerrain;450' from end;125' Right of center;33' high;8:1 clearance slope;Trees;1700' from end;350' Right of center;61' high;24:1 clearance slope;					
Lighting:					
Airport Has Two Rotg Bcns; One on the Airport and One 6500' Southeast Thr Rwy 35. Actvt MIRL Ry 17/35 & REIL Rys 17 & 35 - CTAF. VASI Ry 17 & Ry 35 Oper Continuously.					
Charts: NACO: San Francisco Sectional					
Fees:	Fees: After Hours, Camping, Landing, Overnight, Ramp				
Fuel:	Fuel: 100LL Low-Lead, Jet A				
Phone: 209-533-6684					
Weather: 209-536-9384 (AWOS-3)					
Communication Freqs: 125.1 App/Dep (WEST-NORTH) 124.65 WX 122.975 CTAF 122.975 UNICOM		Elevation: 2121 ft (646.5 m)			
		1	1980 + 58	don 1.08 4073 X75	



35

Clearance Delivery Phone: 916-361-0516;

Notes:

Year-round, 7 Days a Week,0800-1700 All Jet Acft are Requested to Land Ry 35 & Depart Ry 17 Wind & Weather Permitting. Avoid Flights Over Columbia State Park Northeast of Arpt, and Hwy 49 Bridge 5 Nm Southwest of Airport & Vicinity. Calfire Air Tanker Oprs Fm Airport Drg Fire Season. For Clearance Delivery Contact Norcal Approach at 916-361-0516. Hel Prkng Area 300 Ft by 120 Ft (4 Positions). Landing Fee for All Commercial Operators Regardless of Size & Corporate Acft Over 12500 Lbs Gross Landing Weight. Ry 11 Deps Prohibited Due to Conflict with Main Ry. Ry 29 not Recommended for Use During Winter Months Nov Through Mar. Turf Twy North Side of Ry 11/29 not Recommended for Use Nov - Mar Varying Wind Direction & Velocity May be Encountered At Mid Point of Ry 17/35 Due to Terrain Features & Wind Flow Patterns. Ry End Safety Areas Nstd Length; Ry 17 210 Ft; Ry 35 300 Ft. Apch Ratio Fm Dsplcd Thld 31:1. Apch Ratio Fm Dsplcd Thld 37:1. Ry 35 VASI Unusable Byd 5 Deg Left and Right of Ry Cntrln.

FBO's Summary:

Bald Eagle Aviation

Location: CTR Phone: 209-533-4616; Hours: 01/01-12/31, Sun-Sat, 08:30-17:00;

Other (Non-FBO) Businesses Summary:

Sierra Upholstery Location: W

Phone: 209-533-2536; Hours: By Appointment

Springfield Flying Service, LLC

Location: E Phone: 209-532-4103; Hours: 01/01-12/31, Mon-Sun, 08:00-17:00;

Aero Resources, LLC

Location: SE Phone: 209-533-4543; Hours: 01/01-12/31, Mon-Fri, 08:00-17:00;