

PGWT

Francisco Manglona Borja/Tinian Intl
Tinian Island, MP

1.00 mi N of city N14 59.9538' E145 37.1610' Mag Var: 01E

Nav aids:
No Nav aids Available

Traffic Patterns (FAA):
Tfc Pat Alt for Large & Turbine Powered Acft 1532 AGL Sm Acft 1032 AGL
Right: 26 Left: 08


Runways:
Name: Dimensions: Material: Condition: Treatment:
08/26 8600X151 asphalt good grooved
Hill; 1300' from end; 0' of center; 30' high; 36:1 clearance slope;

Lighting:
For REIL Rwys 08 & 26, PAPI Rwys 08 & 26, MIREL Rwy 08/26 CTC Airport 0600-2000 on
CTAF 123.6. for Emergs between 2000-0600 Lgts Can be Reqstd by Ctcg Port Police (670)
433- 9295/9294 or CTAF 123.6.

Charts: NACO: GNC 7 Sectional
Phone: 670-433-9294

Communication Freqs:
123.6 CTAF

Elevation: 270 ft (82.3 m)



Notes:
Year-round, 7 Days a Week,0600-2000
Ap Clsd to Unsked Acr Operations with More Than 10 Pax Seats Excp 24 Hrs Prior
Permission Required Rqrd in Writing to Amgr. P.O. Box 235, Tinian Mp 96952.
Cust Avbl Drg Skedd Opns. Other Times Prior Arngmts Must be Made with Customs Border
Patrol Protection Saipan Call 288-0028.
Ppr Fm Executive Director Commonwealth Ports Authority Saipan Call 664-3500/01/02
Mon-Fri.
Rdo Deadzone on W End of Twy Alpha to Rwy 08.
Arff Svc Avbl 0600-1930 & for Air Carrier Operations with More Than 9 Psgrs Seats.
Exec Dir, Leo B. Tudela (670) 237-6500 Located on Saipan.

