

ALPINE CO (See MARKLEEVILLE on page 206)

ALTURAS

ALTURAS MUNI (AAT)(KAAT) 1 W UTC-8(-7DT) N41°28.97' W120°33.93'

KLAMATH FALLS

4378 B NOTAM FILE AAT

L-11A

RWY 13-31: H4228X50 (ASPH) S-12 MIRL

IAP

RWY 13: Road. Rgt tfc.

RWY 31: REIL. Railroad.

RWY 03-21: H2506X60 (ASPH) S-12 LIRL 0.5% up NE

RWY 03: REIL. VASI(V2L)—GA 3.0° TCH 28'. Railroad.

RWY 21: Tree. Rgt tfc.

SERVICE: FUEL 100LL, JET A LGT ACTVT REIL Rwy 03 and 31; VASI Rwy 03; MIRL Rwy 13-31; LIRL Rwy 03-21—CTAF.

AIRPORT REMARKS: Attended 1600-0100Z†. Deer on and inof arpt.

Wildlife refuges to the SW, S, and SE present potential bird hazards to acft from Oct–April. Firefighting acft seasonal May–Oct. Arrivals Rwy 21 discouraged due to school on apch. No tkf Rwy 03 to NE except during adverse wind conditions. 150' minimum alt over houses.

AIRPORT MANAGER: 530-233-2377

WEATHER DATA SOURCES: ASOS 124.175 (530) 708-6221.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **SEATTLE CENTER APP/DEP CON** 127.6

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE LKV.

LAKEVIEW (VH) (H) VORTACW 112.0 LKV Chan 57 N42°29.57'

W120°30.43' 163° 60.6 NM to fld. 7465/19E.

VOR unusable:

120°–142° byd 40 NM

143°–153° byd 117 NM

143°–153° byd 40 NM blo 11,000'

143°–153° byd 65 NM blo 14,000'

154°–160° byd 40 NM

161°–171° byd 40 NM blo 18,000'

172°–208° byd 40 NM

209°–219° byd 40 NM blo 9,000'

209°–219° byd 63 NM

220°–224° byd 40 NM

225°–236° byd 40 NM blo 15,000'

225°–236° byd 48 NM

237°–248° byd 40 NM

249°–259° byd 40 NM blo 12,000'

249°–259° byd 56 NM

260°–280° byd 40 NM

(DH) DME 116.65 AAT Chan 113(Y) N41°29.00' W120°33.69' at fld. 4378. NOTAM FILE AAT.

DME unusable:

040°–130° byd 30 NM blo 17,800'

220°–230° byd 25 NM blo 10,500'

