EAST HADDAM

GOODSPEED (42B) 1 SE UTC-5(-4DT) N41°26.74′ W72°27.34′

NEW YORK

9 NOTAM FILE BDR

RWY 14-32: H2120X50 (ASPH) S-8 LIRL

RWY 32: Trees.

SERVICE: S4 LGT Arpt lgts opr 24 hrs.

AIRPORT REMARKS: Unattended. Caution deer, birds and waterfowl on and invof arpt. Parl turf twy mkd with yellow cones. May be soft when wet or aft rain. Seaplane dock and ramp. Overnight parking fee. Ldg fee.

AIRPORT MANAGER: (860) 615-9068

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2449.

WATERWAY 16W-34W: 4500X1000 (WATER)

WATERWAY 16W: Bridge. WATERWAY 34W: Hill.

ELLINGTON (7B9) 2 N UTC-5(-4DT) N41°55.53′ W72°27.43′

NEW YORK

253 NOTAM FILE BDR

RWY 01-19: H1800X50 (ASPH) S-9 RWY LGTS(NSTD)

RWY 01: Trees.

RWY 19: Trees.

SERVICE: S4 FUEL 100LL LGT Non-std LIRL opr dusk-0500Z‡, for lgts aft 0500Z‡ call 860-871-2054 durg bus hrs. Rwy 01-19 non-std LIRL due to spacing, thr lgts outboard of rwy.

AIRPORT REMARKS: Attended 1300–2300Z‡. Parachute Jumping. Extensive helicopter training ops. Acft tfc pat on E side of arpt only. Hel tfc pat on W side of arpt only. Twy pavement failed, extsv cracking, patches, loose aggregate and sml stones. Rwy 01 mkgs faded. Rwy 19 mkgs faded.

AIRPORT MANAGER: 860-614-1854

COMMUNICATIONS: CTAF/UNICOM 123.0

CLEARANCE DELIVERY PHONE: For CD ctc Yankee Apch at 860-386-3597.

FARMINGTON CT71 N41°42.54′ W72°48.13′/363 AWOS-AV 129.825 AWOS-AV wx bcst on 129.825 (3 mic clicks). NEW YORK L-33C, 34I

GOODSPEED (See EAST HADDAM on page 35)