

WAAS
CH **45635**
W33A

APP CRS
330°

Rwy Ldg
TDZE **7926**
Apt Elev **7950**

RNAV (GPS) RWY 33
CENTRAL COLORADO RGNL (A.E.J)

NA

-21°C

AWOS-3

132.925

Circling NA northeast of Rwy 15-33. DME/DME RNP-0.3 NA.

When local altimeter setting not received, use Salida altimeter setting and increase all MDA 100 feet. VDP NA with Salida altimeter setting.

#Missed approach requires minimum climb of 425 feet per NM to 14100.

MISSED APPROACH: Climbing right turn to 16000 direct KANON and hold, continue climb-in-hold to 16000.

DENVER CENTER
119.85 363.15

UNICOM
122.8 (CTAF) 0

ELEV **7950**

TDZE **7926**

16000 KANON		VGSi and descent angles not coincident (VGSi Angle 3.00/TCH 41).		BUBYO	
*LNAV only.		*1.8 NM to ROBYV		AKNAC	
ROBYV		330°		338°	
1.3		1.8 NM		3.4 NM	
7.7 NM		10300		12600	
TCH 41		3.44°			
CATEGORY		A	B	C	D
#LP	MDA	8960-1½	1034 (1100-1½)	8960-3 1034 (1100-3)	NA
LP	MDA	9840-1½	1914 (1900-1½)	9840-3 1914 (1900-3)	NA
#LNAV	MDA	9300-1½	1374 (1400-1½)	9300-3 1374 (1400-3)	NA
LNAV	MDA	9980-1½	2054 (2100-1½)	9980-3 2054 (2100-3)	NA
CIRCLING		9980-1½	2030 (2100-1½)	9980-3 2030 (2100-3)	NA

BUENA VISTA, COLORADO

Orig-B 31MAR16

38°49'N-106°07'W

CENTRAL COLORADO RGNL (A.E.J)

RNAV (GPS) RWY 33