

BLAKELY

EARLY CO (BIJ)(KBIJ) 3 E UTC-5(-4DT) N31°23.85' W84°53.69'

JACKSONVILLE
H-9A, 12F, L-22I
IAP

215 B TPA—1202(987) NOTAM FILE MCN

RWY 05-23: H5494X98 (ASPH) S-21 MIRL

RWY 05: PAPI(P2L)—GA 3.0° TCH 34'. Trees.

RWY 23: MALSf. PAPI(P2L)—GA 3.0° TCH 30'. Trees.

SERVICE: FUEL 100LL, JET A LGT ACTVT MALSf Rwy 23; PAPI Rwy 05 and 23; MIRL Rwy 05-23—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1300-2100Z.

AIRPORT MANAGER: 229-723-4304

WEATHER DATA SOURCES: AWOS-3PT 118.475 (229) 723-5511.

COMMUNICATIONS: CTAF 122.9

Ⓡ **CAIRNS APP/DEP CON** 125.4 (24 hrs Tue-Sat, 1200-0500Z Sun-Mon. other times ctc)

Ⓡ **JACKSONVILLE CENTER APP/DEP CON** 134.3

CLEARANCE DELIVERY PHONE: For CD ctc Jacksonville ARTCC at 904-845-1592.

RADIO AIDS TO NAVIGATION: NOTAM FILE ANB.

WIREGRASS (L) (L) VORTACW 111.6 RRS Chan 53 N31°17.08' W85°25.87' 074° 28.4 NM to fld. 345/2E.

VOR unusable:

326°-336° byd 15 NM blo 1,900'


326°-336° byd 20 NM blo 2,300'

326°-336° byd 30 NM blo 4,000'

337°-350° byd 13 NM blo 4,000'

337°-350° byd 20 NM blo 6,000'

337°-350° byd 30



BRANTLEY CO (See NAHUNTA on page 244)

BRUNSWICK GOLDEN ISLES (BQK)(KBQK) 5 N UTC-5(-4DT) N31°15.54' W81°27.98'

JACKSONVILLE
H-9B, 12F, L-24H
IAP, AD

26 B LRA ARFF Index—See Remarks NOTAM FILE BQK

RWY 07-25: H8001X150 (ASPH-GRVD) S-120, D-190, 2S-175,

2D-323 PCR 230 F/B/X/T HIRL

RWY 07: MALSr. PAPI(P4L)—GA 3.0° TCH 58'.

RWY 25: REIL. PAPI(P4L)—GA 3.0° TCH 50'.

SERVICE: S4 FUEL 100LL, JET A LGT Actvt MALSr Rwy 07; REIL Rwy 25; PAPI Rwy 07 and 25; HIRL Rwy 07-25—CTAF.

AIRPORT REMARKS: Attended 1200-0100Z. Deer on and invof arpt. Birds on and invof arpt dur heavy rains and high northeasterly winds. PPR for svc and fuel after hrs call 912-264-9200. Rwy 07-25 full strength shoulders each side. Class I, ARFF Index A. PPR 24 hrs for charter acft ops with more than 30 passenger seats call amgr 912-265-2070. Use caution due to congested airspace with turbine, non-turbine and training acft. KSSI located 7 NM SE. All VFR acft adhere to std left hand tfc pat. All arrivals and dep, including acft flying inst approaches, are requested to report 10 miles from the arpt, intns and psn reports to "Brunswick" CTAF 123.0. Additional arpt safety bulletins posted on arpt website. Flight Notification Service (ADCUS) avbl.

AIRPORT MANAGER: 912-265-2070

WEATHER DATA SOURCES: AWOS-3 124.175 (912) 261-0531.

COMMUNICATIONS: CTAF/UNICOM 123.0

RCO 122.2 (MACON RADIO)

Ⓡ **JACKSONVILLE CENTER APP/DEP CON** 126.75 CLNC DEL 126.75


CLEARANCE DELIVERY PHONE: For CD ctc Jacksonville ARTCC at 904-845-1592.

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE SSI.

(L) (L) **VORTACW** 109.8 SSI Chan 35 N31°03.03' W81°26.76' 359° 12.5 NM to fld. 6/4W.

ILS 108.5 I-BQK Rwy 07. Class IE.



BRUNSWICK N31°03.03' W81°26.76' NOTAM FILE SSI.

JACKSONVILLE

(L) (L) **VORTACW** 109.8 SSI Chan 35 037° 1.7 NM to Jekyll Island. 6/4W.

RCO 122.2 (MACON RADIO)