

MONROE

CHARLOTTE/MONROE EXEC (EQY)(KEQY) 5 NW UTC-5(-4DT) N35°01.04' W80°37.32'

CHARLOTTE

H-9B, 12G, L-25D, 36E

IAP

683 B LRA NOTAM FILE EQY

RWY 05-23: H7001X100 (ASPH) S-35, D-68.5 HIRL 0.3% up SW

RWY 05: MALSR. PAPI(P4L)—GA 3.0° TCH 46'. Trees.

RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Trees.

SERVICE: S4 **FUEL** 100LL, JET A1+ **OX** 3, 4 **LGT** Actvt MALSR Rwy

05; REIL Rwy 23; HIRL Rwy 05-23—CTAF. All lights oper

dusk-0500Z†. After 0500Z†, actvt—122.7. PAPI Rwy 05 & 23 oper consly.

AIRPORT REMARKS: Attended 1200-0000Z†. Deer, wildlife, and birds on and invof arpt. Fuel 24 hr credit card svc avbl. Right side of Twy A at Rwy 23 has steep shoulder drop-off btn rwy and Twy A.

AIRPORT MANAGER: 704-282-4730

WEATHER DATA SOURCES: ASOS 135.775 (704) 283-5185.

COMMUNICATIONS: CTAF/UNICOM 122.7

® **CHARLOTTE APP/DEP CON** 120.05

CLNC DEL 132.55

CLEARANCE DELIVERY PHONE: For CD ctc Charlotte Apch at 704-359-0241.

RADIO AIDS TO NAVIGATION: NOTAM FILE CLT.

(L) (L) **VORW/DME** 115.0 CLT Chan 97 N35°11.42'

W80°57.11' 127° 19.3 NM to fld. 732/5W.

DME portion unusable:

015°-050° byd 25 NM blo 3,000'

050°-100° byd 25 NM blo 2,500'

185°-202° byd 15 NM

203°-220°

270°-350° byd 20 NM blo 5,000'


VOR/DME controlled by charlotte ATCT

VOR unusable:

203°-220°

ILS/DME 109.75 I-EQY Chan 34(Y) Rwy 05. Class IA. LOC unmonitored 2200-1300Z†. LOC unusable byd 30° left of course.

COMM/NAV/WEATHER REMARKS: Arpt phone number 704-282-4730.



MONTGOMERY CO (See STAR on page 365)

MOORE CO (See PINEHURST/SOUTHERN PINES on page 348)