
EASTON STATE (ESW)(KESW) 2 N UTC-8(-7DT) N47°15.25' W121°11.13'

SEATTLE

2226 NOTAM FILE SEA

RWY 09-27: 2640X100 (TURF) LIRL 0.5% up W**RWY 09:** Trees.**RWY 27:** Trees.**SERVICE:** LGT Rwy 09-27 yellow lgts obsc late summer. LIRL Rwy 09-27 opr dusk to dawn when arpt is open.**AIRPORT REMARKS:** Unattended. CLOSED Oct 1-Jun 1; exc apvd MIL and public safety/law enforcement heli ops. PAEW and wildlife on or in/ovf rwy. Fac info prior to use - 360-709-8015 or 1-800-552-0666. Acft acdnt/incidents - 800-258-5990 state emer ops cntr. Wind indicator mounted on 50' twr.**AIRPORT MANAGER:** 360-618-2477**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

EASTSOUND**ORCAS ISLAND** (ORS)(KORS) 1 N UTC-8(-7DT) N48°42.50' W122°54.64'

SEATTLE

35 B TPA-1035(1000) NOTAM FILE ORS

L-1E

RWY 16-34: H2901X60 (ASPH-AFSC) S-12.5 MIRL 0.8% up S

IAP

RWY 16: REIL. PAPI(P4R)-GA 3.48° TCH 35'. Road.**RWY 34:** REIL. PAPI(P2L)-GA 4.0° TCH 42'. Trees. Rgt tfc.**SERVICE:** FUEL 100LL LGT ACTVT REIL Rwy 16 and Rwy 34; PAPI Rwy 16; MIRL Rwy 16-34; twy lgts-CTAF. REIL Rwy 16 and Rwy 34 photocell not avbl durg dalgt. Rwy 34 PAPI unusbl byd 2 degs left of cntrln.**NOISE:** Noise abatement procs in efct - amgr.**AIRPORT REMARKS:** Attended 1600-0030Z†. Deer on and in/ovf rwy. Fuel: 100LL: credit card self svc H24. Ngt circling apch NA fm W side of rwy. Rwy 16-34 markings are faded. Adnl tnst turf tiedowns S of segmented circle. Grass sfc Indg NA. Rwy 34 calm wind rwy.**AIRPORT MANAGER:** 360-376-5285**WEATHER DATA SOURCES:** AWOS-3P 135.425 (360) 376-6045.**COMMUNICATIONS:** CTAF 128.25**MT CONSTITUTION RCO** 122.3 (SEATTLE RADIO)**WHIDBEY APP/DEP CON** 118.2 (ARR and DEP to the South)**VICTORIA TERMINAL APP/DEP CON** 132.7 (ARR and DEP to the North)**CLEARANCE DELIVERY PHONE:** For CD for dep from rwy 16/34, ctc Victoria trml at 604-586-4561.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BLI.**WHATCOM (H) (H) VORTACW** 113.0 HUH Chan 77 N48°56.72' W122°34.76' 203° 19.4 NM to fld. 82/20E.

TACAN AZIMUTH unusable:

155°-165° byd 15 NM blo 6,000'

EATONVILLE**SWANSON FLD** (2W3) 1 NE UTC-8(-7DT) N46°52.30' W122°15.43'

SEATTLE

843 TPA-1643(800) NOTAM FILE SEA

RWY 16-34: H2990X36 (ASPH) MIRL**RWY 16:** Trees. Rgt tfc.**RWY 34:** Ground.**SERVICE:** S4 LGT Arpt lgts opr dusk-0800Z†. After 0800Z†, ACTIVATE MIRL Rwy 16-34-CTAF.**AIRPORT REMARKS:** Attended 1600-0400Z†. Deer on and in vcnty of arpt dusk and dawn. Bldgs are in close proximity to rwy. Annc back taxi on rwy. Grvl svc road arnd Rwy 16-34 not avbl for acft ops. Rwy 16-34 trees in apch and transitional sfcs both sides of rwy. Restrooms avbl at academy NE end.**AIRPORT MANAGER:** 714-686-8480**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle Apch at 206-214-4723.

ED CARLSON MEML FLD/SOUTH LEWIS CO (See TOLEDO on page 285)
