

MOLOKAI

KALAUPAPA (LUP)(PHLU) 2 N UTC-10 N21°12.66' W156°58.42'

24 B TPA—800(776) NOTAM FILE MKK

RWY 05-23: H2700X75 (ASPH) S-17 MIRL**RWY 05:** PAPI(P2L)—GA 3.0° TCH 19'.**RWY 23:** Rgt ttc.**SERVICE:** LGT ACTVT MIRL Rwy 05-23 med instst only—CTAF. PAPI Rwy 05 daytime VFR use only. Rwy 05 PAPI unusbl byd 2.2 NM. Terrain penetrates PAPI safety slope at 2.7 NM. PAPI OTS indefly.**AIRPORT REMARKS:** Attended Mon-Fri 1700-0130Z. PPR from State Department of Health, Communicable Disease Division to enter settlement area phone Honolulu (808) 586-4580. 24 hrs PPR for Division 1.1, 1.2, 1.3 explosives and 4 hrs PPR for other hazardous material in/out of arpt ctc (808) 567-9660/9663. Deer and wild animals on and invof arpt at night. Oct-May large waves impacting shoreline resulting in salt water sprays 40' high. NOTE: See Area Notices—TRAFFIC ADVISORIES AT NON-TOWER ARPTS.**AIRPORT MANAGER:** (808) 872-3830**COMMUNICATIONS:** CTAF 122.9**MOLOKAI RCO** 122.1R 116.1T (HONOLULU RADIO)® **HCF CENTER APP/DEP CON** 124.1**CLEARANCE DELIVERY PHONE:** For CD ctc Honolulu Control Facility at 808-840-6262.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MKK.**MOLOKAI (H) VORTAC** 116.1 MKK Chan 108 N21°08.29' W157°10.05' 057° 11.7 NM to fld. 1421/11E.

VORTAC unusable:

275°-285° byd 25 NM blo 3,500'

HAWAIIAN ISLANDS

P-2G

IAP

