

**RICHLAND MUNI** (M01) 1 N UTC-6(-5DT) N37°52.49' W92°24.48'

KANSAS CITY

1110 NOTAM FILE COU

L-16G

**Rwy 14-32:** H3000X60 (ASPH) S-6 LIRL

**Rwy 14:** Thld dsplcd 170'. Trees.

**Rwy 32:** Thld dsplcd 130'. Trees.

**SERVICE:** LGT ACTIVATE LIRL Rwy 14-32—CTAF.

**AIRPORT REMARKS:** Unattended. Ultralight activity on and invof arpt. Wildlife on and invof arpt. Golfers crossing rwy approximately 800' NW of Rwy 32 thld.


**AIRPORT MANAGER:** 573-765-3532

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD etc Kansas City ARTCC at 913-254-8508.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE COU.

**MAPLES (L) TACAN** Chan 81 MAP (113.4) N37°35.45' W91°47.31' 294° 34.0 NM to fld. 682/6E.



**ROLLA DOWNTOWN** (K07) P 3 SW UTC-6(-5DT) N37°56.14' W91°48.81'

KANSAS CITY

987 NOTAM FILE COU

L-16G

**Rwy 09-27:** H3028X38 (ASPH) 0.3% up E

IAP

**Rwy 09:** Trees.

**Rwy 27:** Thld dsplcd 445'. Trees.

**AIRPORT REMARKS:** Unattended. Wildlife on and invof arpt. Rwy 09-27 line of sight obstructed by grade change in rwy. Tall brush located 70-125' south of rwy, from Rwy 09 thld to access twy. Rwy 09-27 markings faded. Rwy 09-27 pavement cracking, vegetation growing in cracks.

**AIRPORT MANAGER:** 573-430-3065

**COMMUNICATIONS:** CTAF/UNICOM 122.8 UNICOM unmonitored.


**KANSAS CITY CENTER APP/DEP CON** 128.35

**CLEARANCE DELIVERY PHONE:** For CD etc Kansas City ARTCC at 913-254-8508.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE VIH.

**VICHY (L) (L) VORW/DME** 117.7 VIH Chan 124 N38°09.24' W91°42.41' 195° 14.0 NM to fld. 1105/6E.

**COMM/NAV/WEATHER REMARKS:** UNICOM unmon.



**ROLLA NTL** (See ROLLA/VICHY on page 268)