

PORT LAVACA**CALHOUN CO** (PKV)(KPKV) 3 NW UTC-6(-5DT) N28°39.20' W96°40.96'**HOUSTON**H-7C, L-201, 21A, GOAW
IAP

32 B NOTAM FILE PKV

RWY 14-32: H5004X75 (ASPH) S-26 MIRL

RWY 14: PAPI(P2L)—GA 3.0° TCH 45'. Road.

RWY 32: PAPI(P2L)—GA 3.0° TCH 45'. Road. Rgt tfc.

RWY 05-23: 2432X60 (TURF)

RWY 05: Tree.

RWY 23: Thld displcd 428'.

SERVICE: S4 FUEL 100LL, JET A LGT ACTVT MIRL Rwy 14-32—CTAF.

AIRPORT REMARKS: Attended 1400-2300Z†. 100LL and Jet A avbl 24 hrs self serve. Jet A also avbl by truck. RC model acft opr at Rwy 05 end.

AIRPORT MANAGER: 361-552-1228

WEATHER DATA SOURCES: AWOS-3 118.275 (361) 552-3060.


COMMUNICATIONS: CTAF/UNICOM 122.8

® HOUSTON CENTER APP/DEP CON 135.05

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

RADIO AIDS TO NAVIGATION: NOTAM FILE PSX.

PALACIOS (VH) (H) VORTACW 117.3 PSX Chan 120 N28°45.87' W96°18.37' 244° 20.9 NM to fld. 16/8E.

**PORT MANSFIELD****CHARLES R JOHNSON** (TØ5) 1 NW UTC-6(-5DT) N26°33.61' W97°26.36'**BROWNSVILLE**

10 B NOTAM FILE SJT

L-20H, 21A

RWY 12-30: H3200X50 (ASPH) S-21 MIRL

RWY 12: P-line.

RWY 30: P-line.

SERVICE: LGT MIRL Rwy 12-30 preset low intst; to increase intst ACTVT—CTAF.

AIRPORT REMARKS: Unattended. Harbor superintendent's ofc attended 1400-2250Z†. Deer & birds on & invof arpt. Rwy 12 and Rwy 30 rwy mks discolored. Fee for ovnght tie down.

AIRPORT MANAGER: 956-944-2325

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Corpus Christi Apch at 361-299-4230.

RADIO AIDS TO NAVIGATION: NOTAM FILE HRL.

HARLINGEN (VL) (DH) VORW/DME 113.65 HRL Chan 83(Y) N26°13.75' W97°39.14' 025° 22.9 NM to fld. 32/5E.

PORTLAND**HUNT** (9R5) 2 NW UTC-6(-5DT) N27°53.18' W97°20.97'**BROWNSVILLE**

38 NOTAM FILE SJT

RWY 14L-32R: H2350X20 (ASPH) S-9 0.7% up NW

RWY 14L: P-line. Rgt tfc.

RWY 32R: Brush.

RWY 14R-32L: 1400X60 (TURF-GRVL)

RWY 14R: Rgt tfc.

NOISE: Noise abatement procedures in effect. Call arpt manager at 361-643-3950.

AIRPORT REMARKS: Unattended. Rwy 14R-32L CLOSED indef. Wind turbines N of arpt. Rwy 14L-32R has severe grass encroachment, pot holes, and loose gravel on rwy. Rwy 14R-32L heavy rutting along entire rwy length. Rwy 14L-32R limited line of sight between thlds; southern 600' of rwy drops off approximately 8'. Rwy 32R ground drops off approximately 10' at thld.

AIRPORT MANAGER: 361-643-3950

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Corpus Christi Apch at 361-299-4230.

POSSUM KINGDOM (See GRAFORD on page 336)