

E89

Conchas Lake Conchas Dam, NM

1.00 mi SW of city N35 22.0703' W104 10.8305' Mag Var: 10E

Nav aids:

Type:	ID:		Freq:	Radial:	Dist:
VORTAC	TCC	- - - - -	113.60	279	31 nm
VORTAC	ACH	· - - - -	117.80	058	45 nm
VORTAC	FTI	· · · - -	117.30	097	50 nm

Traffic Patterns:

Airport Manager:	Aircraft	Altitude (MSL)
	Light Aircraft	5030

Runways:

09/27: 4800X60; asphalt, no surface treatment, in good condition; Tree, 300 ft Left of center, 70 ft high, 1,980 ft from end, 25:1 clearance slope;

Elevation: 4,232 ft (1,289.9 m)

*Image
Not
Available*

Communication Freqs:

CTAF 122.9

Lights: Actvt ODALS Rys 09 & 27 -
CTAF

Phone: 505-244-1788

Charts: NACO: Albuquerque Sectional

Fuel: Not Reported

Notes/Remarks:

Gate Lock Combination is Set to Field Elevation (4230)

Wildlife on & Invol Airport

Twys Have Retro Reflective Markers