

07R

**Bishop-Windham
Bishop, TX**

3.00 mi NE of city	N27 36.6100'	W97 45.1517'	Mag Var: 07E
--------------------	--------------	--------------	--------------

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOR	ALI	.. _ . _ .	114.5	113	16 nm
VORTAC	CRP	.. _ . _ .	115.5	214	24 nm

Traffic Patterns:

No TPA reported. Assume 1,000 AGL.
Left: 15,33

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
15/33	3200X50	asphalt	fair	no treatment
<i>Road; 519' from end; 155' Left of center; 15' high; 21:1 clearance slope;</i>				
<i>Road; 600' from end; 165' Right of center; 15' high; 26:1 clearance slope;</i>				

Communication Freqs:

122.9 CTAF CD

Charts: NACO: Brownsville Sectional

Phone: 361-584-2567

Clearance Delivery Phone: 281-230-5622;

Notes:

Fuel reserved for Bishop Municipal Airport (07R) based pilots. Transient pilots must call ahead if interested in buying fuel

Unattended

For Clearance Delivery Contact Houston ARTCC at 281-230-5622.

Intensive Mil Jet Tfc 1300 Ft AGL & Abv from Kingsville Nas (Nqi) 7 Nm Sw. CTC
Kingsville Approach 119.9 for Instrns.

Ext 106

Mayor/Amgr.

Mirls Out of service Indefly.

Other (Non-FBO) Businesses Summary:

Bishop Airport

Location: N
Phone: 361-443-9879;

Elevation: 55 ft (16.8 m)

No Diagram Published

