

1W15

Beaver Dam Lake
Randolph, WI

3.00 mi SE of city N43 30.8992' W88 57.1566' Mag Var: 00

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VORTAC	MSN	— ... _.	108.6	034	28 nm
VORTAC	OSH	— — —	116.75	209	33 nm
VORTAC	DLL	_.. _.. _..	117.0	090	35 nm

Traffic Patterns:

No TPA reported. Assume 1,000 AGL.
Left: 05W,23W,09W,27W,18W,36W

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
05W/23W	10000X1000	water	not reported	no treatment
09W/27W	5000X1000	water	not reported	no treatment
18W/36W	5000X1000	water	not reported	no treatment

Charts: NACO: Chicago Sectional

Phone: 414-326-3158

Clearance Delivery Phone: 630-906-8921;

Notes:

Year-round, 7 Days a Week,Daylight
Concrete Ramp Up Onto Shore; Tie Downs on Shore.
For Clearance Delivery Contact Chicago ARTCC at 630-906-8921.
Owner Indicates Pilots Land At Own Risk or Emergency.
In Beaver Dam One 414-326-3158.

Elevation: 871 ft (265.5 m)

No Diagram Published

