

7B2

Northampton
Northampton, MA

1.00 mi NE of city N42 19.6806' W72 36.6744' Mag Var: 15W

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VORTAC	BAF	113.0	039	11 nm
VOR/DME	CTR	115.1	095	15 nm
VOT	BDL	111.4	008	24 nm

Traffic Patterns:

No TPA reported. Assume 1,000 AGL.
Left: 14,32

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
14/32	3335X50	asphalt	good	no treatment
Trees; 600' from end; 210' Right of center; 60' high; 6:1 clearance slope;				
Trees; 1000' from end; 51' Right of center; 32' high; 25:1 clearance slope;				

Lighting:

Actvt MIRL Rwy 14/32 - CTAF.

Charts: NACO: New York Sectional

Fees: Overnight

Fuel: 100LL Low-Lead

Phone: 860-833-7602

Clearance Delivery Phone: 860-386-3597;

FBO's Summary:


Northampton Aeronautics, Inc.

Location: NW
Phone: 413-584-7980; Hours: 01/01-12/31, Mon-Sun, 08:00-17:00;

Communication Freqs:

125.35	App/Dep
133.6	Clearance Delivery
122.7	CTAF
122.7	UNICOM

Elevation: 121 ft (36.9 m)



Notes:

Year-round, 7 Days a Week, 0800-1800
(Pay Phone) Pay Phone Available.
Airport Clsd to All Acft & Hel Crtfyd for 12500 Lbs & Ovr.
Cold Temperature Airport. Altitude Correction Required At or Below -24C.
Fee & Prior Permission Required for Coml Bln Ops.
For Clearance Delivery Contact Yankee Approach at 860-386-3597.
Gldr Act on & In vicinity of Airport May-Oct.
Ldg Fee for Coml Acft.
Richm@Fly7B2.Com
15 Ft Road in Prim Sfc.
Apch 38:1 to Dthr.
Road in Prim Sfc 50 Ft Fm Thr.
Fuel is 24 Hr Self-Serve.

