

7NC2

Pine Island
Corolla, NC

9.00 mi S of city N36 15.2097' W75 47.3114' Mag Var: 09W

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOR/DME	ECG	. _ . _ . _ .	115.75	098	19 nm
VOR/DME	RBX	. _ . _ . . .	111.6	355	20 nm
VORTAC	ORF	_ . _ . . _ .	116.9	159	43 nm

Traffic Patterns (Airport Manager):

Aircraft:	Altitude (MSL):
Light Aircraft	1000
Right: 35 (Assumed Left: 17)	

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
17/35	3450X55	asphalt	not reported	no treatment

Noise Abatements:

RnWy:	Arcrft:	App/Dep:	Noise Abatement:
All	All	Both	Avoid Overflight of Wildlife Sanctuary to the West of the Runway

Charts: NACO: Washington Sectional

Phone: 252-489-1994

Clearance Delivery Phone: 703-771-3587;

Notes:

4/5/17: CAUTION - Seasonally high volume banner tow & air tour traffic, 500'-1000' transitioning the pattern
4/5/17: Arpt attended Intermittent Seasonally
4/5/17: Landing fee for all aircraft, call 252-256-2322
4/5/17: Left Traffic pattern for runway 17
4/5/17: Approach/Departure Facility - NTU
Unattended
For Clearance Delivery Contact Washington ARTCC at 703-771-3587.
Mnt 122.8 for Trfc In vicinity of Dare County Regional Arpt.
Mnt 122.9 When in Tfc Pat.
No Prkg of Acft or Cars.
Written Permission Rqrd to Lnd. Ldg Fees for All Acft. for Airport Operations Rqmnts, CTC
Airport Manager At 252-489-1994 or 919-389-3655
Ry 17/35 All Traffic Remain East of Airport So As to Avoid Wildlife Sanctuary.

Elevation: 16 ft (4.9 m)

No Diagram Published

