C81	Campbell Grayslake, IL
2.00 mi SW of city N42 1	9.4767' W88 4.4453' Mag Var: 02W
Navaids: Morse: Type: ID: Morse: VOR/DME OBK	Frequency:Radial:Distance:113.03218 nm109.220118 nm108.2533921 nm
Traffic Patterns (FAA): TPA: 800' AGL Left: 06,24,09,27	
Runways: Name:Dimensions:Material: Condition:Treatment: o treatment:06/243573X40asphaltfairno treatmentTrees;253' from end;90' Right of center;16' high;15:1 clearance slope; Tree;Tree;1540' from end;86' Left of center;78' high;17:1 clearance slope; no treatment09/273270X40asphaltfairno treatment	
Charts: NACO: Chicago Sectional	
Fuel: 100LL Low-Lead	
Phone: 847-201-1618	
Clearance Delivery Phone: 847-289-0926;	
Campbell Airport Service Location: W Phone: 847-201-1618; Hours: 01/01-12/31, Mon-Fri, 08:30-16:00;	
Communication Freqs: 120.55 App/Dep	Elevation: 788 ft (240.2 m)
122.7 CTAF 122.7 UNICOM	 ✓ ✓
Generated 5/17/2025 at http://www.aopa.org/destinations/airports/C81/details Copyright 2025 Aircraft Owners and Pilots Association	

http://www.aopa.org/destinations/airports/C81/details Copyright 2025 Aircraft Owners and Pilots Association

Notes:

Year-round,Mon-Fri/0830-1600 Year-round,Sat-Sun/Unattended For Clearance Delivery Contact Chicago Approach at 847-289-0926. No Touch & Go Lndg Permitted. Numerous Migratory Birds In vicinity of Arpt. Twys with Nstd Spacing and Clearances In vicinity of Ramp Apron. Unlgtd Power Lines 167 Ft AGL 3/4 Mile S of Rwy 09/27. Email Address: Pjk201@Aol.Com (All Lower Case) Pavement Has Several Areas of Depressions. Rwy Edges Drop Off in Excess of 2 Inches. Southwest 1000 Ft Turf-Grvl. Lirl Spacing & Lgt Intst Varies. Rwy 09 & 27 Nstd Tril Out of service Indefly. Nstd Tril Opr Dusk-Dawn. +15 Ft Rd Adj Rwy End L & R. Apch Ratio 23:1 At Dsplcd Thr. Rwy 24 Nstd Dsplcd Thld White Stripe Mkgs Only. Marked for Ry 06 on Southwest Beginning of Paved Surface. Nstd Tril Opr Dusk-Dawn.