

E61

Conchas Lake  
Conchas Dam, NM

2.00 mi SW of city    N35 23.0529'    W104 12.9819'    Mag Var: 10E

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VORTAC	TCC	— —· —·	113.6	280	33 nm
VORTAC	ACH	— —· ···	117.8	056	44 nm
VORTAC	FTI	··· — ··	117.3	097	48 nm

Traffic Patterns:

No TPA reported. Assume 1,000 AGL.  
(Assumed Left: ALL,WAY)

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
ALL/WAY	21120X1320	water	not reported	no treatment

Communication Freqs:

122.9 CTAF

CD

Charts:

NACO: Albuquerque Sectional

Phone:

575-868-2221

Clearance Delivery Phone:

505-856-4861;

Notes:

Unattended  
Exp Southwest Wind; Rcmnd Lndg & Tkof to the W.  
For Clearance Delivery Contact Albuquerque ARTCC at 505-856-4861.  
Hvy Boat Tfc May-Oct.  
Operations Na North of Dam.  
Water Level Fluctuates 4153-4201 Ft; Lndg Haz Due to Exposed Snags & Land Masses  
Blw 4175 Ft; Mnt Water Level - 575-868-2221, Facebook or Uscgs Website Under Conchas Lake.  
Wind Warning Lgt W of Dam At Lodge; Lgts Flash Gtr Than 20 Mph Wind.  
Emerg - 505-520-8864.  
All/Way Dam 5000 Ft Ne.

Elevation: 4201 ft (1280.5 m)

No Diagram Published

Generated 6/30/2025 at  
<http://www.aopa.org/destinations/airports/E61/details>  
Copyright 2025 Aircraft Owners and Pilots Association

