

E70

Huber Airpark Civic Club Llc
Seguin, TX

2.00 mi NW of city N29 36.1444' W97 59.4338' Mag Var: 06E

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VORTAC	RND	•- -• -••	112.3	067	16 nm
VORTAC	SAT	•• -• -	116.8	088	25 nm
VOT	SAT	•• -• -	110.4	081	25 nm

Traffic Patterns:
No TPA reported. Assume 1,000 AGL.
(Assumed Left: 18,36)

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
18/36	3415X50	asphalt	good	no treatment

Tree; 350' from end; 124' Right of center; 35' high; 4:1 clearance slope;

Communication Freqs:

122.9 CTAF

CD

Lighting:

Actvt Lrl Rwy 18/36 - CTAF.

Charts:

NACO: San Antonio Sectional

Fees:

After Hours, Facility, Hangar, Landing, Landing, Parking

Fuel:

100LL Low-Lead

Phone:

830-379-9800

Clearance Delivery Phone:

210-805-5516;

Notes:

Year-round, Mon-Fri/0800-1700
For Clearance Delivery Contact San Antonio Approach at 210-805-5516.
Or 619-228-5885 Manager Cell. Derrick@Veracityaviation.Com
Only Cntr 3285 Ft Lgtd.
Rwy Mag Brg 174/354.
Rwy 18, 5 Ft Fence 122 Ft Dstc; 18 Ft Road 164 Ft Dstc Acrs Apch.
Rwy 36, 7 Ft Crops 0-199 Ft Dstc, Acrs Apch, Seasonal.
Fuel Self-Serve.

FBO's Summary:

Veracity Aviation

Location: N
Phone: 830-379-9800; Hours: 01/01-12/31, Sun-Sat, 08:00-17:00;

SVT Aviation Maintenance, LLC

Location: CTR
Phone: 210-744-8631; Hours: 01/01-12/31, Mon-Fri, 08:00-17:00;

Elevation: 556 ft (169.5 m)

No Diagram Published

Generated 5/14/2025 at
<http://www.aopa.org/destinations/airports/E70/details>
Copyright 2025 Aircraft Owners and Pilots Association

