FL37

Treasure Coast Airpark Port St. Lucie, FL

17.00 mi NE of city N27 14.4517' W80 29.3150' Mag Var: 03W

Navaids:

Distance: Type: ID: Morse: Frequency: Radial: VÖRTAC **TRV** 117.3 187 26 nm VOR/DME PHK 115.4 021 29 nm PBI 115.7 331 40 nm VORTAC

Traffic Patterns:

No TPA reported. Assume 1,000 AGL.

(Assumed Left: 10,28)

Runways:

Name: **Dimensions: Material: Condition:** Treatment: 10/28 4061X48 asphalt not reported no treatment

Communication Freqs:

122.9 CTAF CD

Lighting:

Actvt MIRL Rwy 10/28 - CTAF. Charts: NACO: Miami Sectional

Phone: 561-603-3343

Clearance Delivery Phone: 561-275-1430;

Notes:

Unattended

Actvt Pcl for All Opns, Inclg Day Vmc.

Airport Ltd to Acft with A Max Crtfyd Tkof Wt (Mtow) of 12500 Lbs (5670 Kg) or Less.

Be Alert for Wildlife on Rwy.

Cmnc All Turns Byd Airport Bndry.

For Clearance Delivery Contact Palm Beach Approach at 561-275-1430

Skid Equipped Hels are Prohibited Fm Running Tkofs or Ldgs, Inclg Practice Autorotation,

on All Sfcs.

Trees Alg Both Sides of Rwy.

Rwy 10/28 Nstd MIRL Due to Nstd Spacing.

Elevation: 29 ft (8.8 m)

No Diagram Published

