

KBLU

Blue Canyon - Nyack  
Emigrant Gap, CA

1.00 mi S of city    N39 16.4983'    W120 42.5850'    Mag Var: 16E

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOR/DME	SWR	... _ . _ .	113.2	270	21 nm
VOR/DME	HNW	.... _ . _	115.5	346	33 nm
VOR/DME	MYV	_ _ . _ _ ... _	110.8	059	42 nm

Traffic Patterns (Airport Manager):

Aircraft:	Altitude (MSL):
Light Aircraft	6284
Left: 15,33	

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
15/33	3300X50	asphalt	good	no treatment
Tree; 750' from end; 110' Left of center; 20' high; 27:1 clearance slope;				
Tree; 400' from end; 0' Both-Sides of center; 15' high; 13:1 clearance slope;				

Communication Freqs:

120.075    WX	122.9    CTAF
---------------	---------------

Lighting:

Rotg Bcn Out of service Indefly .

Charts:    NACO: San Francisco Sectional

Phone:    530-745-3576

Weather: 530-212-0347 (ASOS)

Clearance Delivery Phone:    510-745-3380;

Notes:

Unattended  
Airport Clsd Ss-Sr.  
Do not Attempt to Land with Snow on the Runway. No Snow Removal Services are Provided.  
For Clearance Delivery Contact Oakland ARTCC at 510-745-3380.  
Located At Dept of Public Works Office, Auburn, Ca.  
Rwy 15 +4 Ft Brush 100 Ft Fm Thld 125 Ft Left to 125 Ft Right

Elevation: 5284 ft (1610.6 m)

No Diagram Published

