

KGDV

Dawson Community
Glendive, MT

4.00 mi NW of city N47 8.3233' W104 48.4333' Mag Var: 10E

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
DME	GDV	— · — · — · —	114.35	342	0 nm

Traffic Patterns:
No TPA reported. Assume 1,000 AGL.
Left: 02,20,12,30

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
02/20	3002X60	asphalt	good	no treatment
12/30	5704X100	asphalt	good	grooved


Lighting:
Activate MIRL Rwy 02-20 and Rwy 12-30, PAPI Rwy 02 and Rwy 20, REIL Rwy 12 and Rwy 30 - CTAF. VASI Ry 12/30 Oper Continuously.

Charts: NACO: Billings Sectional
Fees: Hangar, Landing, Overnight, Ramp
Fuel: 100LL Low-Lead
Phone: 406-989-2054

Weather: 406-687-3346 (AWOS-3PT)

FBO's Summary:
Dawson County FBO
Location: SE
Phone: 406-687-3372; Hours: 01/01-12/31, Sun-Sat, 07:00-20:00;

Communication Freqs:
135.075 WX
122.8 CTAF
122.8 UNICOM



Notes:
Security Directive SD-8G
Year-round, 7 Days a Week,0730-1830
Airfield Surface Conditions Unmonitored 0100-1100 Nov-May.
For Cd If Una to CTC on FSS Freq, CTC Salt Lake ARTCC at 801-320-2568.
After Hrs Contact Airport Manager 406-989-2054.
Twy A Has Edge Lips Exceeding 3 In.

