

5.00 mi SW of city N37 38.9972' W97 25.9826' Mag Var: 04E

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOT	ICT	.. _.. _	114.0	003	1 nm
VORTAC	ICT	.. _.. _	113.8	122	9 nm
VOR/DME	HUT _.. _	116.8	127	32 nm

Traffic Patterns:

No TPA reported. Assume 1,000 AGL.
Right: 19R,01R Left: 01L,19L,14,32

Runways:


Name:	Dimensions:	Material:	Condition:	Treatment:
01L/19R	10302X150	concrete	good	grooved
01R/19L	7302X150	concrete	good	grooved
14/32	6301X150	concrete	good	grooved

Tower:

Primary Approach Control Hrs: 24
Primary Depart. Control Hrs: 24
Tower Hrs: 24
Said In Use. Operate Transponders With Altitude Reporting Mode And Ads-B (If Equipped)
Enabled On All Airport Surfaces.

Charts: NACO: Wichita Sectional**Fees:** Deicing, Deicing I, Deicing II, GPU, GPU, Handling, Infrastructure, Landing, Lavatory, Lavatory,
Preheat, Ramp, Tie Down**Fuel:** 100LL Low-Lead, Jet A**Phone:** 316-946-4700**Weather:** 316-800-1006 (ASOS)**Communication Freqs:**

125.5 App
(270-009 BLW 5000 FT & BYD 20 NM)
134.85 App/Dep (010-190)
126.7 App/Dep IC (191-009)
125.15 ATIS
126.7 CLASS C (191-009)
134.8 CLASS C (010-190 4000 FT & BLW)
134.85 CLASS C (010-190 ABV 4000 FT)
125.7 Clearance Delivery
121.5 Emergency
121.9 Ground Control
118.2 Tower
122.95 UNICOM

Elevation: 1333 ft (406.3 m)**Notes:**

Year-round, 7 Days a Week, All
Acft Parking Bas Contact 132.00 for Parking Instructions Prior to Exiting Twy L1.
Air Cargo Ramp Clsd to Acft Wingspan More Than 148 Ft.
Aircraft Engine Runs Above Idle not Approved on Aircraft Parking Ramps.
Atct Has Ltd Vis of Trml Gates 1 Thru 8, Twy H, and Customs Prkg Ramp.
Attended Continuously.
Call for Gate Pushback not Required.
Flight Notification Service (Adcus) Avbl.
Migratory Birds on and in Vicinity of Arpt, All Quads.
Ppr Required for Acft Carrying Class 1 Division 1.1, 1.2 or 1.3 Explosives As Defined by 49 Cfr 173.50 or As Amended.
Twy H Clsd to Acft with Wingspan More Than 79.
Twy L and L1 Clsd to Acft with Wingspan More Than 118.
Twy P Clsd to Acft with Wingspan More Than 79.
Twys F, G, H, J, P and All Acft Parking Ramps are Nonmovement Areas.

FBO's Summary:**Yingling Aviation**

Location: N
Phone: 316-943-3246; Hours: 01/01-12/31, Sun-Sat, 00:00-23:59;

Signature Flight Support

Location: N
Phone: 316-522-2010; Freq: ARINC: 130.570; Hours: 24/7

Other (Non-FBO) Businesses Summary:**Bevan Aviation Inc.**

Location: N
Phone: 316-946-4870; Hours: 01/01-12/31, Mon-Fri, 08:00-16:30;

FlightSafety International

Location: N
Phone: 316-220-3100; Hours: 01/01-12/31, Mon-Fri, 08:00-17:00;

Hawker Beechcraft Global Customer Support, LLC

Location: N
Phone: 316-676-4503; Freq: ARINC: 130.570; Hours: 01/01-12/31, Mon-Thu, 00:00-00:00;
01/01-12/31, Fri-Sun, 07:00-19:30;

Bombardier Aerospace / Learjet, Inc

Location: NW
Phone: 316-946-2287; Hours: 24/7

Textron Aviation Employees' Flying Club

Location: N
Phone: 316-515-7232; Hours: 1/1-12/31, Mon-Fri, 08:30-16:30;

Mid-Continent Aviation Services

Location: N
Phone: 316-927-4207; Hours: 01/01-12/31, Mon-Fri, 08:00-17:00;

Ortega Aviation Services

Phone: 316-925-7700; Hours: 01/01-12/31, Mon-Fri, 09:00-17:00;

Aviation Academy, LLC

Phone: 316-285-5413; Hours: 24/7

