

KMCD

Mackinac Island
Mackinac Island, MI

1.00 mi NW of city N45 51.8990' W84 38.2257' Mag Var: 07W

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VORTAC	PLN	•— •— •—	111.8	011	14 nm
VOR/DME	SSM	 —	112.2	206	35 nm

Traffic Patterns (FAA):

TPA: 1159' AGL
Left: 08,26

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
08/26	3501X75	asphalt	good	porous friction course
Tree; 374' from end; 290' Left of center; 29' high; 6:1 clearance slope;				
Tree; 491' from end; 275' Left of center; 34' high; 8:1 clearance slope;				

Lighting:

Actvt REIL Rwy 08 & 26; PAPI Rwy 08 & 26; MIRL Rwy 08/26 - 122.8.

Charts: NACO: Lake Huron Sectional

Fees: Landing, Overnight

Phone: 906-847-3231

Weather: 906-847-3778 (AWOS-3)

Clearance Delivery Phone: 651-463-5588;

FBO's Summary:


Mackinac Island Airport

Location: CTR
Phone: 906-847-3231; Hours: 01/01-12/31, Mon-Sun, 08:00-17:00;

Communication Freqs:

118.275 WX
122.7 CTAF
122.7 UNICOM

Elevation: 741 ft (225.9 m)



Notes:

Year-round, 7 Days a Week,0800-1700
For Clearance Delivery Contact Minneapolis ARTCC at 651-463-5588.
Lrg Birds on & In vicinity of Arpt; Flocks of Seagulls In vicinity of Landfill 0.3 Nm Ne.
Noise Abatement Procs: Climb to TPA Bfr Turning; Avd Flt Ovr Shore & Town; Tgl Na.
Obstn Lgts are in the Approach to Rwy 26.
Pitot Cvs Rcmdd While Parked; Ck Tubes Bfr Dep Due to Mud Daubers.
+4 Ft Fence, 0 Ft Dist, 210 Ft L/R.
Papi Unusbl Byd 5 Degs Left of Cntrln.
Papi Unusbl Byd 5 Degs Left of Cntrln.

