

0.00 mi NW of city N39 7.3761' W94 35.5694' Mag Var: 01E

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOT	MKC	— —· —·—	108.6	094	0 nm
VORTAC	MCI	— —· —·—	113.25	140	12 nm
VORTAC	ANX	· —· —·—	115.15	268	22 nm

No TPA reported. Assume 1,000 AGL.
Left: 19,04,22 (Assumed Left: 01)

Name:	Dimensions:	Material:	Condition:	Treatment:
01/19	6827X150	concrete	excellent	grooved

Tree: 747' from end; 571' Right of center; 38' high; 20:1 clearance slope;
Road: 700' from end; 150' Left of center; 20' high; 25:1 clearance slope;

04/22 5050X100 asphalt excellent no treatment
Berm; 450' from end; 125' Left of center; 20' high; 12:1 clearance slope;
Railroad; 225' from end; 100' Left of center; 37' high; 0:1 clearance slope;

Tower Hrs: 24
Interference From Fm Radio Station May Affect Communications In The Immediate Vicinity Of
The Arpt.


Fees:	Airport and Operations, Deicing I, Deicing IV, Facility, GPU, Handling, Infrastructure, Landing Lavatory, Parking, Preheat, Ramp, Ramp, Security, Tie Down
--------------	---

Phone: 816-859-7610

Weather: 816-329-2843 (ASOS)

118.4 App/Dep
120.75 WX
120.75 ATIS
120.95 BRAYMER STAR
121.9 CD PRE TAXI CLNC
121.9 Ground Control
120.95 JHAWK STAR
133.3 Tower
120.95 TYGER STAR
122.95 UNICOM

Elevation: 757 ft (230.7 m)



Year-round, 7 Days a Week, All
Atct Has Limited Visibility of T-Hangar Aprons N Twy D and W Twy L .
Ctn: Mult Obstructions 0.5 Mi-1.0 Mi Ese Fm Rwy 19 Der Up to 290 Ft AGL/1100 Ft MSL.
Due to Obstns, Prior to Any Turns to the E, Acft Must be At or Abv Tfc Ptn Alt
FAA Safety Video Can be Accessed At
https://www.faa.gov/airports/runway_safety/videos/mkc/
Flocks of Pigeons In vicinity of Dep Eor 04.
Rwy 04/22 VFR E Tfc Pat: Departing Rwy 04 Right Tfc Attain Tfc Pat Alt Prior to Turning
Crosswind. Ldg Rwy 22 Mntn Tfc Pat Alt Until Passing N of Missouri River.
Wildlife on & In vicinity of Arpt.
Airport Clsd to Acr Operations with More Than 30 Psgr Seats Excp 24 Hr Prior Permission
Required Call Airport Manager (816) 289-2718. Air Carrier Operations not Authorized in
Excess of 15 Minutes Bfr or Aft Sked Arr or Dep Times W/O Prior Coordination with Airport
Manager Confirming Arff Avbl Prior to Lndg or Tkof.
Pcr Value: 784/R/D/W/T
Pcr Value: 560/F/C/X/T
Engineered Materials Arresting Sysytem (Emas) 263 Ft in Length by 170 Ft in Width Lctd
At the Der 01.
Apch Ratio At Dsplcd Thr 47:1.
Engineered Materials Arresting Sysytem (Emas) 287 Ft in Length by 170 Ft in Width Lctd
At the Der 19.
Road & Fence 0-200' Fm Thr.
Ry19 Malsf Augmented with Rail.
Apch Ratio At Dsplcd Thr 24:1.
Road & Rr 0-200' Fm Thr.
Unusbl Byd 8 Degs Left of Crs.
100LL Self Svc Avbl 24 Hrs with Credit Card Only on West Side Near Ga Terminal.

Signature Flight Support

Location: SE
Phone: 816-842-8484; Freq: ARINC: 129.575; Hours: 24/7

Location: NW
Phone: 816-949-8900; Freq: ARINC: 129.100; Hours: 01/01-12/31, Sun-Sun, 00:00-23:59;

Location: NW
Phone: 816-859-7600; Hours: 01/01-12/31, Sun-Sat, 00:00-23:59;

Other (Non-FBO) Businesses Summary:

Little Blue Aviation

Phone: 913-226-7199; Hours: By Appointment

ATD Flight Systems, LLC

Location: S

Phone: 816-221-8455; Hours: 01/01-12/31, Sun-Sat, 08:00-17:00;

J H Aviation

Phone: 816-510-5950; Hours: By Appointment

Signature TECHNICAir

Location: W

Phone: 816-842-3500; Freq: ARINC: 129.575; Hours: 01/01-12/31, Mon-Sun, 08:00-16:30;

Duncan Aviation, Inc.

Location: S

Phone: 816-421-1836; Hours: Irregular

Aviation Institute of Maintenance - Kansas City

Phone: 816-753-9920; Hours: 01/01-12/31, Mon-Thu, 08:30-20:00; 01/01-12/31, Fri-Fri, 08:30-17:00;

US Flight Co

Phone: 816-542-7525; Hours: 24/7

Midwest Pilot Training

Phone: 816-889-8906; Hours: 01/01-12/31, Mon-Sun, 07:00-17:00;

Skybound Helicopters

Location: E

Phone: 888-759-4354; Freq: ARINC: 129.575; Hours: 01/01-12/31, Mon-Sun, 08:00-22:00;

