

KRIL

Rifle Garfield County
Rifle, CO

3.00 mi E of city N39 31.5964' W107 43.6792' Mag Var: 10E

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOR/DME	RIL	..- .- .-..	113.35	245	0 nm
VOR/DME	EKR	..- .- .-..	115.2	155	34 nm
VOR/DME	SXW	... -.- -.-	109.2	248	35 nm

Traffic Patterns:

No TPA reported. Assume 1,000 AGL.
Right: 26 Left: 08

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
08/26	7000X100	asphalt	good	grooved

Lighting:

Actvt ODALS Rwy 26; REIL Rwy 08; HIRL Rwy 08/26 - CTAF. PAPI Rwy 08 & 26 on Consly.

Charts:

NACO: Denver Sectional

Fees:

After Hours, Airport and Operations, Facility, Parking, Security

Fuel:

100LL Low-Lead, Jet A

Phone:

970-625-1091

Weather:

970-625-2206 (ASOS)

FBO's Summary:

Atlantic Aviation


Location: SE

Phone: 970-625-4833; Hours: 01/01-12/31, Sun-Sat, 07:00-20:00;

Communication Freqs:

135.275 WX
122.8 CTAF
122.8 UNICOM

Elevation: 5537 ft (1687.7 m)



Notes:

Year-round, 7 Days a Week, All
For Acft Gwt 10000 Lbs or More.
Aft Winter Sn Storms Airport Operations Bfr All Twys are Cleared.
Cold Temperature Airport. Altitude Correction Required At or Below -13C.
Ctn: Sn Removal Equip Operations Fm 1 Oct to 15 May.
Flw FAA Procs for Non-Towered Arpts.
For Cd, Ifun to CTC on Denver ARTCC App/Dep Ctl Freq, CTC Denver ARTCC at 303-651-4257.
Gld Operations In vicinity of Arpt.
Iftr Atc Clnr Fm Ril is not Authority to Enter Rwy or Tkof & Lndg.
Ovngr Prkg Fee.
Proper Dual Rdo Use (Atc/CTAF) is Esntl for Safe and Efficient Tfc Flow.
Saturated Pat Policy: Tgls Prohibited When 5 or More Acft in Tfc Pattern.
Use CTAF Prior to Entering Rwy or Pat.
Airport Ops-24 Hrs / 970-230-1685.

Other (Non-FBO) Businesses Summary:

Colorado Flight Center

Location: SE
Phone: 970-254-0444; Hours: 01/01-12/31, Mon-Fri, 09:00-17:00;

