

KSKF

Kelly Fld San Antonio, TX

4.00 mi SW of city N29 23.0540' W98 34.8670' Mag Var: 04E

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOR	SSF	108.4	307	10 nm
VOT	SAT	... -	110.4	213	11 nm
VORTAC	SAT	... -	116.8	194	17 nm

Traffic Patterns (FAA):

Rectangular 1700' MSL, Convl 2200' MSL, r Type/Ovhd 2700Ft MSL
Aetc Acft Exp Reduced Rwy Separation Day/VFR
Tran'r Acft Must Notify Twr on Initial CTC of Reduced Separation is not Desired
Left: 16,34

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
16/34	11550X150	concrete	good	grooved

Tower:

Tower Hrs: 24
AfrC Comd Post: (433 Aw) Not For Trans Aircraft Use.
Joint Base San Antonio Comd Post: (502 Abw) Dsn 471-9363, C210-221-9363.
Pmsv: Full Svc H24 Unless Afld Clsd By Amops Via Notam. Wx Dsn 945-5709
C210-925-5709. Afld Wx Is Mnt By An/Fmq-19 Asos. Remote Briefing Svc Avbl 26 Ows,
Barksdale Afb Dsn 331-2651, C318-529-2651.

Charts: NACO: San Antonio Sectional

Fees: After Hours, Airport and Operations, Facility, GPU, Lavatory, Parking

Fuel: 100LL Low-Lead


Phone: 210-362-7838

FBO's Summary:

Atlantic Aviation

Location: E
Phone: 210-921-6100; Freq: ARINC: 129.725
Hours: 01/01-12/31, Sun-Sat, 06:00-23:00;

Elevation: 691 ft (210.6 m)



Notes:

Civilian Ramp Ltcd Northeast of Ry. Ga Ramp Access Via Twys A1, B and C.
Contact Port San Antonio Operations 210-362-7837/7838.
Cstms/Ag/Img: Cstms, Plant Quarantine and Img Avbl, CTC Amops by Fone Patch or Ptd
Rdo 2 Hr Before Arr. All Pers, Excl'd Active US Mil, Must Clear Img Inbd.
Customs/Ag/Img Rqr 72 Hrs Pn CTC FBO. J8-Atlantic Avn, 1200-0600Z++, 2 Hr Pn for
Defueling and Reservice.
Military Service: Fluid - Sp Presair Lhox Lox Lhnit.
Military Service: Fuel- A++, A+. Mil Fuel Unavbl Sat 0400-1200Z++.
Military Service: Jasu -(A/M32A-86D, A/M32A-95 Lass).
Military Service: Oil - O-133-148-156; Soap - Avbl 2000-0600Z++ Mon; 1230-0600Z++
Tue-Thur; 1230 - 2230Z++ Fri.
Military Service: Tran Alert - Opr 1130-0430Z++ Mon-Fri, 1330-0230Z++ Sat-Sun, Clsd
Federal Hol; Ot 2 Hr Pn Rqr CTC Amops. 1 Hr Pn for All Acft Svc; CTC Amops Dsn
945-6802, C210-925-6802 or Ptd to Avoid Delays. Una to Support Tran Acft Lcl Sorties.
Military-Misc: USAF Tran Acft Will Use Tran Alert Svc and Park on Mil Ramp. Non-USAF
Tran Acft May Prk At Mil Ramp or Atlantic Aviation FBO on Civ Ramp; for Qns CTC
Airfield Mgmt Operations C210-925-6803.
Misc: Acft with Code 6 and Abv CTC Amops Fone Patch/Ptd with Block Time At Least 1
Hr Before Ldg.
Misc: Ltd Classified Mtrls Storage: Excess and Ts Mtrls Must Go to 433 Aw/Cp.
Misc: Official Point of Observation Does not Allow A Clear Unobstructed View of Rwy. Wx
Technician View from N to Southeast is Partially Obstructed by Trees, Bldgs, & Hangars.
Technician Relies on Cooperative Wx Watch with Twr. High Intensity Security Lgts Hinder
Ability to Determine Sky Cond At Night.
Misc: Rwy Cond Code (Rwycc) not Rprtd.
Misc: Tacan Ck Point/Altm Sign on Twy F and B Sited Opposite Drctn of Tacan.
Port Operations 210-362-7875.
Rstd: Quiet Hrs 0500-1200++ Dly Dep and Full Stop Ldg Only.
Rstd: Tran Acft Exp Delays and May be Ltd to One Approach to A Full Stop for Home
Stn Formal Trng Unit Operations and Tactical Arr and Dep Trng Mon-Fri 1500-0400Z ++.
Rstd:Req for Prior Permission Required Will be Taken No Earlier Than 7 Days Prior to
Planned Mission. At Least 24 Hr Pn Rqrd for Ppr, Exc Medevac, Dv and Other Acft on A
Case by Case Basis Apvd by Do. CTC Base Operations Dsn 945-6803, C210-925-6803.
Prior Permission Required Good for +1/-1 Hr Prior Permission Required Block Time. Coord
of Prior Permission Required Outside of Block Time by Fone is Rqrd.
Rwy: All Rwy Grooved.
Service-Lgt: Rwy 34 PAPI Ltcd Nstd on Rgt (East) Side of Rwy 34.
Service-Lgt: Twy F: No Twy End Lgts.
Twy G West of Twy H is for 149Fw Use.
User Fees Applicable to Civil Acft.
Warning: Large Successive Flocks of Cattle Egrets, 5 to 50 in No., Have Been Observed
Flying Blw 300 Ft AGL Across N End of Rwy Ev Morning At Sr for Up to 2 Hrs,
Returning Within 2 Hr of Ss. Bash Ph II in Eff 1 Mar-30 Nov. Caution: North End
Underrun/Ovrn 147' Paved, 853' Unpaved. Runway and Majority of Taxiway Pavement
Shoulders Exceed Standard Dimensions and are not Marked with Yellow Chevron Deceptive
Surface Markings to Indicate Unusable.
For Civilian Operations, Contact Port Operations 210-362-7875.
Bak-14 Bak-12A(B) (1853').
Bak-14 Bak-12A(B) (1677') Hook Mb100 (60' Ovrn).
Landing Fee for All Acft Excluding U.S. Mil and Acft Less Than 12,500Lbs. Invoiced by Psa
Airport Department, law Jua
Acft Using Avgas Self-Serve: Do not Deviate Fm Tax Lns To/Fm Avgas Self-Serve to
Ensure Safe Dstc Fm Other Opns. 100LL Fuel is Self Serve At Port San Antonio and Full
Service At FBO.



Notes:
Year-round, 7 Days a Week,All
Cstms; Plant Quarantine & Img Svc Avbl CTC Base Operations 2 Hrs Pn. All Psnl Must
Clear Img Inbd.
US Customs User Fee Arpt.
A-Gear: Bak-12A(B) Cables Raised by Bak-14 Device O/R to Ctl Twr. Potential for Hook
Skip At Bak-12 Cable Sys Due to Irreg Edges and Uneven Depths Wi 200 Ft of Arresting
Sys
Acft Arr between 0500-1200Z++ Exp Full Stop Ldg. No After Burner Tkof Dur These Times
Wo Prior Coord and Apvl.
Acft with Wing Span Larger Than 93 Ft not Authorized in Arm/Dearm Pads.
Afrc: Prior Permission Required for Use of Afrc Ramp, Dsn 945-4330, C210-925-4330.
Ang: Opr 1345-2230Z++ Tue-Sat. Prior Permission Required for Use of Ang Ramp, Dsn
945-5934, C210-925-5934.
Apn Psa Ramp Clsd in Both Drctns At Twy B At Apn Entrance to Twy C to All Acft
Unless Under Tow.
Bearing Strength Rwy 16/34 - St175 Sbt590 Ddt870 Trt580.
Caution: Hvy Rubber Deposits Obscuring Rwy Mrkgs At Tdzs
Caution: Inst Hold Line Mrk Faded on Twy F.
Caution: Probability of Hydroplaning At All Speeds Entire Rwy.

Other (Non-FBO) Businesses Summary:

Standard Aero, Inc

Location: E
Phone: 210-334-6000;

Bario Aviation

Location: NE
Phone: 830-460-9028; Hours: 01/01-12/31, Mon-Sat, 08:00-19:00;

