

KTTD

Portland-Troutdale  
Portland, OR

10.00 mi E of city    N45 32.9617'    W122 24.0750'    Mag Var: 16E

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOT	PDX	•—• —• —•—	111.0	108	9 nm
VORTAC	BTG	—•• — —••	116.6	125	14 nm
VOT	HIO	••• • —•—	115.2	088	23 nm

Traffic Patterns:

No TPA reported. Assume 1,000 AGL.  
Left: 07,25

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
07/25	5399X150	asphalt	good	no treatment
Trees; 2100' from end; 0' Both-Sides of center; 105' high; 18:1 clearance slope;				
Trees; 1653' from end; 0' Both-Sides of center; 63' high; 23:1 clearance slope;				

Tower:

Tower Hrs: 0700-2200

Lighting:

Actvt MIRL Ry 07/25 - CTAF. Ry 07 VASI & Ry 25 PAPI Oper Cont.

Charts: NACO: Seattle Sectional

Fees: After Hours, Landing, Overnight, Parking, Ramp

Fuel: 100LL Low-Lead, Jet A

Phone: 503-415-6119


Weather: 503-492-2887 (ASOS)

Clearance Delivery Phone: 503-493-7545;

Communication Freqs:

118.1	App (100-279, HIGH)
124.35	App/Dep
135.625	WX
135.625	ATIS
120.9	CTAF
121.8	Ground Control
124.35	HELNS STAR
124.35	OCITY STAR
120.9	Tower
122.95	UNICOM

Elevation: 39 ft (11.9 m)



Notes:

Landing fee for commercial aircraft and other aircraft with a max gross landing weight greater than 10,000 pounds  
Year-round, 7 Days a Week,0700-2200  
Avoid Low-Level Overflights of Residential Areas.  
Extensive Helicopter Operations on and Adjacent to West Ends of the Parallel Twys, No Early Turnouts.  
For Clearance Delivery Contact Portland Approach at 503-493-7545.  
Migratory Flocks of Waterfowl on & In vicinity of Arpt.  
Multiple Const Cranes 110 Ft AGL or Blo Located 2700 Ft Southwest of Ry 25 Thld.  
Noise Abatement Procedures in Effect. Call 503-460-4100 or 800-938-6647.  
Noise Sensitive Areas Border the Airport West and South.  
Portland International Airport Ry 10L/28R Extndd Centerline Crosses Arpt, Air Traffic Control Tower May Issue Restrictions Due to Pdx Tfc.  
Recommend Between Ss and Sr, Ry 7 Left Tfc and Ry 25 Right Tfc Due to Bluff 5000 Ft South of Arpt.  
Aph Cln Slope from Dthr is 45:1 Based on 21' Road At 817'.  
Aph Ratio 27:1; Dike At 588' Lgtd.  
Ry 25 PAPI is Baffled 08 Deg L and R of Cntrln.  
Commercial Acft & Operators of Acft with an FAA Certified Max Gross Landing Weight That Exceeds 10000 Lbs are Required to Pay A Landing Fee.

FBO's Summary:

Gorge Winds Aviation, Inc.

Location: N  
Phone: 503-661-1044; Hours: 01/01-12/31, Mon-Fri, 07:00-17:30; 01/01-12/31, Sat-Sun, 08:00-17:00;

Other (Non-FBO) Businesses Summary:

Premier Aircraft Engines, Inc.

Location: N  
Phone: 503-661-4184; Hours: 01/01-12/31, Mon-Fri, 08:00-16:30;

Troutdale Aircraft Services

Location: NW  
Phone: 503-666-3838; Hours: 01/01-12/31, Mon-Fri, 08:00-17:00;

Dash Air, Inc.

Location: SE  
Phone: 503-492-0406; Hours: 01/01-12/31, Mon-Fri, 08:00-17:00;

Emerald Aircrafters

Location: NE  
Phone: 503-667-3282; Hours: 01/01-12/31, Mon-Fri, 08:00-17:00;

Hillsboro Aero Academy

Location: SE  
Phone: 503-489-1142; Hours: 01/01-12/31, Mon-Sun, 08:00-17:00;

