

PASC

Deadhorse
Deadhorse, AK

0.00 mi SE of city N70 11.6852' W148 27.9099' Mag Var: 17E

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOR/DME	SCC	... _.- _.-	113.9	238	1 nm

Traffic Patterns:
No TPA reported. Assume 1,000 AGL.
Right: 06 Left: 24

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
06/24	6500X150	asphalt	good	grooved

Lighting:
When FSS Clsd Acvt MALSR Rwy 06 & 24; HIRL Rwy 06/24 - CTAF. HIRL Rwy 06/24 Preset Low Intst; Incr Intst - CTAF.

Charts: NACO: Point Barrow Sectional

Fees: After Hours, Deicing, Ramp

Fuel: 100 Octane, Jet A


Phone: 907-328-7130

Weather: 907-659-2591 (ASOS)

FBO's Summary:
Colville, Inc.
Phone: 907-659-6215; Hours: 01/01-12/31, Sun-Sat, 06:00-18:00;

Communication Freqs:
118.4 WX
123.6 CTAF
123.0 UNICOM

Elevation: 67 ft (20.4 m)



Notes:
Year-round, 7 Days a Week,0600-1830
Airport Maint 0600-1830; Aft Hr - Amgr.
Arff Svc Prior Permission Required in Writing - Amgr.
Aviation Cntr Pvt Prior Permission Required - 907-538-3600.
Colville Ramp Clsd.
Tsa Regulated; See 49 Cfr 1542. All Gates & Doors Must be Secured At All Times. Tsnt or Unfamiliar Pilots - Airport Manager for Info.
Waterfowl In vicinity of Arpt; Caribou on Rwy & Mov Areas.
Wx Camera Avbl on Internet At [Https://Weathercams.FAA.Gov](https://Weathercams.FAA.Gov)
Wx Obs When Deadhorse FSS Clsd - 133.55 or 907-659-2401.
Clsd to Acr Operations More Than 30 Pax Seats Exc Prior Permission Required in Writing - Airport Manager Po Box 340002 Prudhoe Bay Ak 99734.
Pcr Value: 801/F/A/X/T
0600-1800 - 122.85 or 907-659-6215.

