

PWAK

Wake Island Airfield
Wake Island, QW

0.00 mi N of city N19 16.9497' E166 38.1990' Mag Var: 06E

Nav aids:
Type: VORTAC **ID:** AWK **Morse:** _ _ _ _
Frequency: 113.5 **Radial:** 109 **Distance:** 1 nm


Traffic Patterns:
No TPA reported. Assume 1,000 AGL.
Left: 10,28

Runways:
Name: 10/28 **Dimensions:** 9844X150 **Material:** asphalt **Condition:** not reported **Treatment:** no treatment

Charts: NACO: GNC 7 Sectional
Phone: 8084242101200

Weather: (AWOS-3P)

Communication Freqs:



Notes:
Exc Hol
Year-round, Mon-Sat/2000Z-0400Z
Arresting Gear - (Rwy 28) Hook Bak 12B (4921').
Be Alert to Bird Hazard on Approach to Ry 10 and Ry 28 Dep.
Be Alert to Ocean Vessels with Mast Aprx 125 Ft Periodically Lctd At Mooring Buoys 3600 Ft W of Thld Ry 10.
Caution: Airfield Has Mixture of Regular and Led Obst Lgt. Led Obst Lgts May not be Visible to Some Nvd.
Ctc Wake Island Airport Operations on 128.0/349.4.
Email for Prior Permission Required Req Form: Prscdet1.Airfield.Management@Us.Af.Mil. After Prior Permission Required Apvl, Pwak Eta/Etd Deviations Byd 2 Hr Rqr Reapproval. Base Operations Fone Dsn 315-424-2101, C808-424-2101, Fax Dsn 315-424-2165.
Fuel: Flight Crew Required to Assist in Refueling. J5(Mil). Fluid - W, Sp, Presair.
Misc: Etops Divert Lctn. Firefighting Services Reduced to Nfpa Cat 7, Arff Index C.
Misc: Remote Wx Briefings Avbl H24 Fr 17 Ows At Dsn 315-449-8333/7950 or 448-3809, 2Hr Ntc Rqr for Timely Brief. When Nml Satcom O/S, Imarsat is Avbl. Space Avbl Pax are Na to Ron.
Rstd: Prior Permission Required for All Acft At Least 24 Hr in Advance. Prior Permission Required Phone Only Dsn 424-2101, C808-424-2101, Fax Dsn 315-424-2165, C808-424-2165, or E-Mail: Baseops@Wakeisland.Net .
Rstd: Emerg Divert Acft Outside Publ Airfield Hrs, CTC FAA Controller At Oakland ARTCC to Arrange Base Ops/Atc Specialist Personnel Recall Via Wake Fire Dispatch At Fone 808-424-2911 Pri or 808-424-2232 Sec.
Rstd: No Aircraft Maintenance Avbl. Taxiway Line Restriction Located At Intersection of Taxiway Echo and Delta. Continues (West) Onto the Warm-Up Pad Does not Provide Wingtip Clearance to Aircraft with Wingspan Greater Than 60 Feet.
Rstd: Very Limited Operations Status, Avbl for Emerg Ldg and Min Priority Tfc.
Rwy - Caution: 4 Ft X 8 Ft Area of Gradual Pavement Rise (Hump) of Aprx 2 Inches Lctd 2300 Ft E of Approach End Rwy 10, 40 Ft Rgt of Cntln.
Service - Fuel: Acft Refueling At Pwak: Site Arr Req Must be Obtained from 907-552-5781 and Submitted for Apvl Prior to Arr.
Service-Lgt: Several Obst Lgt O/S: Controlling Obst Lgt Tower 101 Ft AGL Aprx 1700 Ft S of Rwy 28 Thld.
Service-Tran Alert: Lav Svc Unavbl.
Tfc Pat: Rgt Break Ry 10 All Acft, Left Break Ry 28 All Acft.
Tran Alert: Svcb Fees Rqd. Tran Svc Hrs 2000-0400Z (0800L-1600L) Tue-Sat. Clsd Sun, Mon, Hol.
Airport Will be Considered A Joint Use Airport Open to Civil Acft Subject to Mil Reqrmts.
Base Operations - 808-424-2101/2000
900' Coral Overrun.

