

TUPJ

Terrance B Lettsome Intl
Roadtown,

8.00 mi E of city N18 26.7333' W64 32.5000' Mag Var: 13W

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOR/DME	STT	... - -	108.6	089	28 nm
VOR/DME	COY	-. - _ _ _	108.2	022	43 nm

Traffic Patterns:
No TPA reported. Assume 1,000 AGL.
(Assumed Left: 07,25)

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
07/25	4645X98	asphalt	not reported	no treatment

Tower:
Tower Hrs: 1100-0200Z UTC-4

Lighting:
Dusk-0200Z Utc-4.

Fuel: 100 Octane, Jet A1

Phone: 1-284-852-9000

Other (Non-FBO) Businesses Summary:

Platinum BVI Services
Location: NE
Phone: 284-346-1298; Hours: 01/01-12/31, Mon-Sun, 09:00-19:00;


Airport Services (BVI) Ltd
Phone: 284-495-1796;

Signature Flight Support
Phone: 284-495-0303;

Elevation: 16 ft (4.9 m)

No Diagram Published

Generated 5/25/2025 at
<http://www.aopa.org/destinations/airports/TUPJ/details>
Copyright 2025 Aircraft Owners and Pilots Association



Notes:
Disclaimer. The information and data contained herein for Caribbean/Bermuda airports have been provided by entities outside of, and not under the control of, the Federal Aviation Administration (FAA). Therefore, the information and data have not been verified by the FAA and are provided "as is," without any representation or warranty that they are accurate, reliable, complete, or up-to-date. Your use of this data and this website constitutes your acknowledgement of this limitation. The reproduction, publication, or dissemination of this information and data, in whole or in part, is not authorized.
Beaches, resorts, yacht charters, fishing, and snorkeling
14.7 KM (8 nm) E of Roadtown
ATTD year-round, 7 days/wk, 1100-0200Z. TWR hours: 1100-0200Z. Lighting schedule Dusk-0200Z
0700Z. All arriving/departing are req to file flight plan via tower@bvია.com at least 1HR b/4 ETA/D. RWY 7 normally used for TKOF & landing. Occasional wind shear on APC to RWY 7 when winds are from the S or SE. Obstructions: AD is surrounded by high terrain. Pilots must be knowledgeable of the surrounding terrain. Unmarked high terrain located within 4 NM radius at 1263 ft. IFR ops require knowledge of AD hazard lighting and APC pattern. Contact the AD administration for more info. At least two day (VFR) landings are required to qualify for night landing ops. Potential of light to moderate turbulence on final to RWY 7/25 when wind is between 090 and 180 degrees at 15 kts or greater. Firefighting equipment on field. Bird hazard.
100LL, Jet A
TUPJ customs office open M-Su 1100 - 0200. Call airport admin or FBOs for more information
Year-round, seven days a week,1000-0200Z UTC-4. TWR hours: 1100-0200Z UTC-4
BVI Airports Authority Phone: (284) 394-8000
Limited repair for light ACFT with arrangement
Snacks and vending avbl at FBOs. Full service restaurant in main terminal
Buses, taxis, limousine services and car rental: Virgin Car Hire (284) 494-2999
Year-round, 7 Days a Week,1000-0200Z UTC-4
Bird Haz.
Foreign Civ Govt. Lndg Fees & Diplomatic Clnc May be Rqr.
Ocnl Wind Shear on Approach Ry 07 When Winds are Fm S & Se.
Papi.
Papi.