

W50

Davis  
Laytonsville, MD

3.00 mi N of city    N39 14.5938'    W77 9.0508'    Mag Var: 09W

Nav aids:

Type:	ID:	Morse:	Frequency:	Radial:	Distance:
VOR	FDK	··· ·· ··	109.0	142	15 nm
VORTAC	EMI	· — ··	117.9	216	17 nm
VORTAC	BAL	··· ·· ··	115.1	292	23 nm

Traffic Patterns (FAA):

TPA: 800' AGL  
Left: 08,26

Traffic Patterns (Airport Manager):

Aircraft:                      Altitude (MSL):  
Light Aircraft                      1430

Runways:

Name:	Dimensions:	Material:	Condition:	Treatment:
08/26	2600X50	asphalt	good	no treatment
Trees; 716' from end; 75' Left of center; 57' high; 9:1 clearance slope;				
Trees; 836' from end; 177' Left of center; 51' high; 12:1 clearance slope;				

Communication Freqs:

122.8 UNICOM                      122.8 CTAF  
CD

Charts:    NACO: Washington Sectional

Fees:      Overnight, Tie Down

Fuel:      100LL Low-Lead

Phone:    301-253-2897

Clearance Delivery Phone:    866-429-5882;

Notes:

Year-round, Mon-Fri/Dawn-Dusk  
Unicom Unmon.  
Airport Clsd Dusk-Dawn.  
Birds & Wildlife on & In vicinity of Arpt.  
For Clearance Delivery Contact Potomac Approach at 866-429-5882.  
Touch & Go Operations Na.  
Pond 80 Ft R of Thr.

FBO's Summary:

Davis Flying Services

Location: NE  
Phone: 301-253-2897; Hours: 01/01-12/31, Mon-Fri, Dawn-Dusk;

Elevation: 609 ft (185.6 m)

No Diagram Published

