

# KINL

## Falls Intl-Einarson Field International Falls, MN

0 mi S of city N48 33.9350' W93 24.1300' Mag Var: 03E

### Nav aids:

Type:	ID:	Freq:	Radial:	Dist:
VOR/DME INL	.. - - . - - .	111.0	089	0 nm
VOR/DME BDE	- - . - - .	111.60	097	49 nm

### Traffic Patterns:

Airport Manager:	Aircraft	Altitude (MSL)
	Light Aircraft	2185

### Runways:


- 04/22:** 2999X75; asphalt, no surface treatment, in fair condition;
- 13/31:** 7400X150; asphalt, porous friction course, in good condition;

### Communication Freqs:

WX 120.0T  
CTAF 122.8  
UNICOM 122.8

**Lights:** Actvt MALSR Ry 13/31; PAPI  
Ry 13/31; HIRL Ry 13/31 - CTAF

**Elevation: 1,185 ft (361.2 m)**



**Phone:** 218-283-4461

**Weather:** 218-285-2996 (ASOS)

**Fees:** Parking, Tiedown, Hangar

**Charts:** NACO: Twin Cities Sectional

**Fuel:** 100LL Low-Lead, Jet A

### Notes/Remarks:

- Cold Temperature Restricted Airport. Altitude Correction Required at or Below -31c
- Gulls & Deer on & Invol Arpt
- Security Directive SD-8G

### Business Summary

#### Einarson Flying Service

Fuel: Unknown-100LL; Unknown-Jet-A  
Location: NE; Hours: 5:00 AM - 10:00 PM  
Frequencies: Unicom: 122.8  
Phone Number: 218-283-4461