

KINL

Falls Intl-Einarson Field International Falls, MN

0 mi S of city N48 33.9350' W93 24.1300' Mag Var: 03E

Nav aids:

Type:	ID:	Freq:	Radial:	Dist:
VOR/DME INL	.. -.- .-.-	111.0	089	0 nm
VOR/DME BDE	-... -... .	111.60	097	49 nm

Traffic Patterns:

Airport Manager:	Aircraft	Altitude (MSL)
	Light Aircraft	2185

Runways:


04/22: 2999X75; asphalt, no surface treatment, in fair condition;
13/31: 7400X150; asphalt, porous friction course, in good condition;

Communication Freqs:

WX 120.0T
CTAF 122.8
UNICOM 122.8

Lights: Actvt MALSR Rwy 13, 31;
HIRL Rwy 13/31; PAPI Rwy 13 - CTAF.
PAPI Rwy 31 Opr Consly

Elevation: 1,185 ft (361.2 m)



Phone: 218-283-4461

Weather: 218-285-2996 (ASOS)

Fees: Parking, Tiedown, Hangar

Charts: NACO: Twin Cities Sectional

Fuel: 100LL Low-Lead, Jet A

Notes/Remarks:

Cold Temperature Restricted Airport. Altitude Correction Required at or Below -31c

Gulls & Deer on & Invol Arpt

Security Directive SD-8G

Business Summary

Einarson Flying Service

Fuel: Unknown-100LL; Unknown-Jet-A

Location: NE; Hours: 5:00 AM - 10:00 PM

Frequencies: Unicom: 122.8

Phone Number: 218-283-4461

