



ILS RWY 16 (SA CAT I & II)
NORTHWEST FLORIDA BEACHES INTL (ECP)

MAISR

MISSED APPROACH: Climb to 600 then climbing left turn to 4000 on heading 025° and on MAI VORTAC R-237 to OLISS INT/MAI 33 DME and hold, continue climb-in-hold to 4000.

CLNC DEL
123.75

LOCALIZER 111.15
I-PUK
Chan 48 (Y)



	6 NM		5.9 NM		1069'	
CATEGORY	A	B	C	D		
S-ILS 16	SA CAT I RA 151/14 150 DA 219					
S-ILS 16	SA CAT II RA 101/12 100 DA 169					

SA CATEGORY I & II ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED