

BRODHEAD (C37) 2 S UTC-6(-5DT) N42°35.73' W89°22.88'

CHICAGO

792 TPA—1592(800) NOTAM FILE GRB

RWY 09-27: 2440X155 (TURF) LIRL(NSTD) 0.3% up W

RWY 09: Trees.

RWY 27: Trees.

RWY 03-21: 1500X100 (TURF) 0.3% up SW

RWY 03: Trees.

RWY 15-33: 1380X100 (TURF) 0.4% up SE

RWY 33: Trees.

SERVICE: S2 LGT ACTIVATE LIRL Rwy 09-27—CTAF. Rwy 09-27 NSTD LIRL spacing.

AIRPORT REMARKS: Unattended. Deer invof movement areas. Rwy's not plowed in winter, open to ski acft. Irrigation equipment near movement areas. Rwy 03-21 mkd with red & white half barrels. Rwy 09-27 mkd with red & white half barrels. Rwy 33 marked with concrete pad. Crop dusting ops in area.

AIRPORT MANAGER: 571-266-2094

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

BROOKFIELD**CAPITOL DRIVE** (Ø2C) 3 E UTC-6(-5DT) N43°05.38' W88°10.77'

CHICAGO

844 B TPA—1644(800) NOTAM FILE GRB

L-28H, A

RWY 09-27: 3387X100 (TURF)

RWY 09: Brush.

RWY 27: Trees.

RWY 03-21: H2994X45 (ASPH) MIRL 0.5% up SW

RWY 03: Thld dsplcd 1378'. Brush.

RWY 21: Thld dsplcd 694'. Brush.

RWY 18-36: 1602X80 (TURF) 0.9% up S

RWY 18: Tree.

RWY 36: Brush.

SERVICE: FUEL 100LL, MOGAS LGT ACTIVATE MIRL Rwy 03-21—CTAF.

AIRPORT REMARKS: Attended Apr-Oct 1400Z±-dusk, Nov-Mar 1400-0000Z±. Rwy 03 and Rwy 36 acft ops cannot see Rwy 27 acft ops. Rwy 09-27 and Rwy 18-36 opn for ski equipped acft Dec 1 thru Apr 15. Rwy 09-27 and Rwy 18-36 not snd or plwd. Cfm conds and sn removal for Rwy 03-21 with amgr 262-781-4213. Rwy 09-27 and Rwy 18-36 mkd with yellow cones. Rwy 03-21 markings faded.

AIRPORT MANAGER: 262-781-4213

COMMUNICATIONS: CTAF/UNICOM 122.7

CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

RADIO AIDS TO NAVIGATION: NOTAM FILE MKE.

BADGER (H) (H) VORW/DME 116.4 BAE Chan 111 N43°07.01' W88°17.06' 107° 4.9 NM to fld. 1070/2E.

BURBUN N42°41.36' W88°18.11' NOTAM FILE BUU.

CHICAGO

(T) DME 114.5 BUU Chan 92 at Burlington Muni. 772.

L-28H, A

BURLINGTON MUNI (BUU)(KBUU) 1 NW UTC-6(-5DT) N42°41.44' W88°18.28'

CHICAGO

780 B NOTAM FILE BUU

L-28H, A

RWY 11-29: H4300X75 (ASPH) S-20 MIRL

IAP

RWY 11: REIL. PAPI(P2L)—GA 3.5° TCH 36'.

RWY 29: REIL. PAPI(P2L)—GA 3.25° TCH 46'. Tree. Rgt tfc.

RWY 01-19: 2410X130 (TURF)

RWY 19: Rgt tfc.

SERVICE: S4 FUEL 100LL, JET A+ ØX 4 LGT MIRL Rwy 11-29 preset to low SS-SR; to incr intst and actvt REIL Rwy 11 & 29; MIRL Rwy 11-29—CTAF. PAPI Rwy 11 and 29 opr consly.

AIRPORT REMARKS: Attended 1400Z±-Dusk. Waterfowl on and invof arpt. 100LL: 24 hr self svc fuel avbl with credit card. Tfc departing Rwy 11 avoid overflight of city. Departing tfc climb to 1000' AGL before turning south. Asph twy 30' wide, except W 700' 35' wide. Rwy end 01 and Rwy end 19 mkd with yellow/black wooden panels.

AIRPORT MANAGER: 262-342-5003

WEATHER DATA SOURCES: AWOS-3 125.275 (262) 757-0907.

COMMUNICATIONS: CTAF/UNICOM 123.05

® MILWAUKEE APP/DEP CON 135.875

GCO 121.725 (FLIGHT SERVICES)

CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

RADIO AIDS TO NAVIGATION: NOTAM FILE BUU.

BURBUN (T) DME 114.5 BUU Chan 92 N42°41.36' W88°18.11' at fld. 772.

BADGER (H) (H) VORW/DME 116.4 BAE Chan 111 N43°07.01' W88°17.06' 180° 25.6 NM to fld.

1070/2E. NOTAM FILE MKE.