

ILS RWY 5L (CAT II & III)
INDIANAPOLIS INTL (IND)

MISSED APPROACH: Climb to 1700 then climbing left turn to 3000 direct VHP VORTAC then on VHP VORTAC R-303 to KEADY/VHP 4.9 DME/RADAR and hold.

MISSED APCH FIX

KEADY
VHP 116.3
RADAR

123°
303°
Chan 110

OINKK INT
I-IND 6.1
RADAR

STDUM
I-IND 9
RADAR

(IF)
FTBLL
I-IND 12.1
RADAR

(IAF)
WAAYN
I-IND 15.2
RADAR 210K

5000 to WAAYN
004° (0.9) and
LOC (10.1)

(IAF)
KELLY
VHP 27.9

(CFVDC)

2300°

25 NM
VHP 116.3
Chan 110

3100 MSA

RADAR or DME REQUIRED

ALTERNATE MISSED
APCH FIX

115.3 TTH
R-077
Chan 100

077°
257°
CLOTT
TTH 23.3
RADAR

Procedure NA for arrivals at
KELLY on V11 southwest bound
and V12 westbound.

ELEV 796

TDZE 747

EC-2, 12 JUN 2025 to 10 JUL 2025