V

DEPARTURE ROUTE DESCRIPTION

<u>TAKEOFF RUNWAY 13:</u> Climb on heading 134° or as assigned by ATC, thence. . . <u>TAKEOFF RUNWAY 31:</u> Climb on heading 314° to 1800 before turning left or as assigned by ATC, thence. . .

. . .expect RADAR vectors to cross CUZNO at or above 3000, then on track 357° to cross NANDR at or below 13000, then on assigned transition.

EAKER TRANSITION (NANDR3.EAKER)
MC ALESTER TRANSITION (NANDR3.MLC)
OKMULGEE TRANSITION (NANDR3.OKM)
ROLLS TRANSITION (NANDR3.ROLLS)
TULSA TRANSITION (NANDR3.TUL)
WILL ROGERS TRANSITION (NANDR3.IRW)
ZEMMA TRANSITION (NANDR3.ZEMMA)