V

## DEPARTURE ROUTE DESCRIPTION

AL-5889 (FAA)

TAKEOFF RUNWAY 33: Climb heading 343° to 9100, then climbing left turn to 16000 on heading 273° to intercept I-PKN NW course outbound to LINDZ INT/DBL 13 DME. Then on assigned transition, maintain 16000, expect clearance to filed altitude 10 minutes after departure.

LOST COMMUNICATIONS: If no transmissions are received for one minute after departure or by DBL VOR/DME 9 DME, turn left on heading 273° to intercept and proceed via the I-PKN NW course (outbound) to LINDZ INT/DBL VOR/DME 13 DME, then via assigned route/transition.

<u>GRAND JUNCTION TRANSITION (LINDZ1.JNC)</u>: From over LINDZ on DBL R-244 to SLOLM, then on JNC R-060 to JNC VOR/DME.

KREMMLING TRANSITION (LINDZ1.RLG): From over LINDZ on SXW R-196 to SXW VOR/DME, then on SXW R-001 to JESIE, then on RLG R-260 to RLG VOR/DME.

<u>MEEKER TRANSITION (LINDZ1.EKR)</u>: From over LINDZ on DBL R-244 to SLOLM, then on RIL R-153 to RIL VOR/DME, then on RIL R-334 and EKR R-155 to EKR VOR/DME.

<u>RED TABLE TRANSITION (LINDZ1.DBL)</u>: From over LINDZ on DBL R-244 to DBL VOR/DME.

<u>RIFLE TRANSITION (LINDZ1.RIL)</u>: From over LINDZ on DBL R-244 to SLOLM, then on RIL R-153 to RIL VOR/DME.