SAIPAN ISLAND

COMMONWEALTH HEALTH CENTER HELIPORT (C21) 1 E UTC+10

HAWAIIAN-MARIANA

N15°12.59′ E145°43.47′

16 NOTAM FILE HNL Not insp.

HELIPAD H1: H45X45 (CONC)

HELIPORT REMARKS: Attended continuously. Rwy H1 110' hotel bldgs west and 85' water tank east of helipad.

AIRPORT MANAGER: (670) 234-8950 COMMUNICATIONS: CTAF 125.7

FRANCISCO C ADA/SAIPAN INTL (GSN)(PGSN) 4 SW UTC+10 N15°07.21′ E145°43.80′ HAWAIIAN-MARIANA

214 B TPA—See Remarks LRA Class I, ARFF Index D

P-1A IAP

NOTAM FILE GSN

RWY07-25: H8699X200 (ASPH-GRVD) S-87, D-175, 2D-350, 2D/2D2-690 PCR 715 F/A/X/T HIRL

RWY 07: MALSR. REIL. Rgt tfc.

RWY 25: REIL. PAPI(P4L)—GA 3.0° TCH 75'

RWY 06-24: H7001X100 (ASPH) PCN 67 R/A/X/T MIRL

RWY 06: Thid dsplcd 396'.

RUNWAY DECLARED DISTANCE INFORMATION

 RWY 06:
 TORA-7001
 TODA-6800
 ASDA-6645
 LDA-6600

 RWY 07:
 TORA-8699
 TODA-8669
 ASDA-8664
 LDA-8010

 RWY 28:
 TORA-6400
 TODA-7001
 ASDA-6302
 LDA-7000

 RWY 25:
 TORA-8699
 TODA-8699
 ASDA-8045
 LDA-8010

SERVICE: FUEL 100, 100LL, JET A1+ LGT SS-SR. Rwy 07 VASI and glidepath not coincident.

AIRPORT REMARKS: Attended continuously. PPR from Executive Director Commonwealth Ports Authority Saipan call (670) 237–6500 Mon–Fri 2130–0630Z other times call 670-237-6535. For Apt Security call (670) 237–6529. Immigration and Customs available during scheduled operations. Other times prior arrangements must be made with CBP port director call (670) 288–0025/26. Rwy 06–24 open for taxiing only (not avbl for lng and tkof). Open for ldg and tkof when Rwy 07–25 clsd. Class I, ARFF Index D. Clsd to unsked acr opns with more than 30 psgr seats exc PPR call or write amgr 670–237–6500/670–287–8881 (cell). P.O. Box 501055 Saipan MP 96950. TPA—Traffic pattern altitude

for large and turbine powered acft 1699(1485), small aircraft 1199(985).

AIRPORT MANAGER: (670) 237-6500

WEATHER DATA SOURCES: ASOS (670) 288-5017. SAWRS.

COMMUNICATIONS: ATIS 127.2

R Guam Cerap App/Dep con 118.4

Tower 125.7 GND con 121.8

AIRSPACE: CLASS D SVC RADIO AIDS TO NAVIGATION:

SAIPAN NDB (HW) 312 SN N15°06.68′ E145°42.62′ 066° 1.2 NM to fld. 83/2E.

ILS/DME 109.9 I-GSN Chan 36 Rwy 07. Glideslope unusable byd 9 NM.

SAIPAN N15°06.68′ E145°42.62′ NOTAM FILE GSN

HAWAIIAN-MARIANA

NDB (HW) 312 SN 066° 1.2 NM to Francisco C Ada/Saipan Intl. 83/2E.

P-1A