

MOSES LAKE

GRANT CO INTL (MWH)(KMWH) 5 NW UTC-8(-7DT) N47°12.52' W119°19.15'

SEATTLE
H-1C, L-13A
IAP, AD1189 B ARFF Index—See Remarks NOTAM FILE MWH
RWY 14L-32R: H13503X200 (CONC-GRVD) S-85, D-155, 2S-175,
2D-320, 2D/2D2-600 PCN 103R/B/W/T HIRL

RWY 14L: REIL. PAPI(P4L)—GA 3.0° TCH 75'. Bldg.

RWY 32R: MALSR. PAPI(P4L)—GA 3.0° TCH 76'. Rgt tfc.

RWY 04-22: H10000X100 (CONC-GRVD) S-75, D-100, 2S-127,
2D-175, 2D/2D2-475 PCN 92 R/B/W/T MIRL

RWY 04: REIL. PAPI(P4L)—GA 3.0° TCH 49'. 0.4% down.

RWY 22: REIL. VASI(V4L)—GA 3.0° TCH 50'. Rgt tfc. 0.3% up.

RWY 09-27: H3500X90 (CONC-GRVD) S-100, D-150, 2S-270,
2D-270, 2D/2D2-475 PCN 53 R/B/W/T RWY LGTS(NSTD)
0.3% up NW

RWY 27: Rgt tfc.

RWY 18-36: H3327X75 (ASPH) S-75, D-170, 2S-175, 2D-300,
2D/2D2-400 PCN 112F/A/W/T MIRL

RWY 18: Rgt tfc.

RWY 14R-32L: H2936X75 (CONC) S-100, D-200, 2S-175, 2D-400,
2D/2D2-400 PCN 107R/B/W/T

RWY 14R: Ground. Rgt tfc.

LAND AND HOLD—SHORT OPERATIONS

LDG RWY	HOLD—SHORT POINT	AVBL LDG DIST
RWY 04	14L-32R	4700
RWY 14L	04-22	7550
RWY 22	14L-32R	4650
RWY 32R	04-22	5050

RUNWAY DECLARED DISTANCE INFORMATION

RWY 04: TORA-10000 TODA-10000 ASDA-10000 LDA-10000

RWY 09: TORA-3500 TODA-3500 ASDA-3500 LDA-3500

RWY 14L: TORA-13503 TODA-13503 ASDA-13503 LDA-13503

RWY 14R: TORA-2936 TODA-2936 ASDA-2936 LDA-2936

RWY 22: TORA-10000 TODA-10000 ASDA-10000 LDA-10000

RWY 27: TORA-3500 TODA-3500 ASDA-3500 LDA-3500

RWY 32L: TORA-2936 TODA-2936 ASDA-2936 LDA-2936

RWY 32R: TORA-13503 TODA-13503 ASDA-13492 LDA-13492

SERVICE: S4 FUEL 100LL, JET A, A1+ 0X1 LGT ACTVT MALSR Rwy 32R; REIL Rwy 04; PAPI Rwy 14L—CTAF. Rwy
09-27 mil ldg zone lgts only.

AIRPORT REMARKS: Attended continuously. Rwy 09-27 CLOSED exc mil ops; C-17 assault strip. Not vis fm ATCT. Birds invof
arpt Apr and Oct. Rwy 14L conc tdz fst 3240 ft; Rwy 32R conc tdz fst 1490 ft. Class IV, ARFF Index A. PPR for air carrier
ops with gtr than 30 pax seats 0600-1400Z† - 509-762-5363. ARFF dep Index D H24. Twy F not vis fm ATCT. No
edge intensity lgts. Rwy 32R fst 10,000' grvd 150' wide. Twy G unlighted. Hvy mil jet ngt training 0300-1100Z†. When
ATCT clsd annnc Indg intns—CTAF. Hvy jet trng sfc to 5000' wi 25 mi; psbl wake turb fm Rwy 09-27 and Rwy 14L-32R.
Acr twy mov area only. All rapid rfl mil hel acft ctc—C509-762-2222 or 131.625 for svc one hr prior to Indg. Procd to
trml ramp. Rapid rfl avbl dalgt dly. Ldg fee. Landing fees ovr 12,500.

AIRPORT MANAGER: 509-762-5363

WEATHER DATA SOURCES: ASOS 119.05 (509) 762-5082. LAWRs.

COMMUNICATIONS: CTAF 118.25 ATIS 119.05 UNICOM 122.95


MOSES LAKE RCO 122.4 (SEATTLE RADIO)

® GRANT COUNTY APP/DEP CON 126.4 (1400-0600Z†)

® SEATTLE CENTER APP/DEP CON 126.1 (0600-1400Z†)

TOWER 128.0 (WEST) 118.25 (EAST) (1400-0600Z†) GND CON 121.9

AIRSPACE: CLASS D svc 1400-0600Z†; other times CLASS E.



CONTINUED ON NEXT PAGE

