

SILETZ BAY STATE (See GLENEDEN BEACH on page 176)**SILVER LAKE F S STRIP** (45S) 3 SW UTC-8(-7DT) N43°06.66' W121°05.65'**KLAMATH FALLS**

4492 NOTAM FILE MMV

RWY 03-21: 3000X55 (TURF-DIRT)**RWY 03:** Fence.**RWY 21:** Fence.

AIRPORT REMARKS: Unattended. Rwy soft when wet, call 541-576-7520 for current cond. Rwy sfc bumpy when dry. Rwy 03-21 weed growth and sage throughout primary sfc. Rwy 03 outlined with white tires. Rwy 03-21 has fence post at each end of rwy painted orange and white.

AIRPORT MANAGER: 541-912-7439**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**SISTERS EAGLE AIR** (6K5) 1 N UTC-8(-7DT) N44°18.27' W121°32.35'**KLAMATH FALLS**

3168 NOTAM FILE MMV

RWY 02-20: H3560X60 (ASPH) S-4**L-1B****RWY 02:** Thld dsplcd 340'. Tree.**RWY 20:** Trees.**SERVICE:** FUEL 100LL

AIRPORT REMARKS: Unattended. Deer on and invof arpt. Rising terrain off departure end of Rwy 02. Check density alt/acft performance prior to tkl. Avoid overflights of homes to northeast. Pilots may consider a departure climb over meadow approximately 45° to the left of the departure end of Rwy 02. Rwy has w and yellow sidestrips and markings.

AIRPORT MANAGER: (541) 719-0602**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RDM.

DESCHUTES (VH) (H) VORTACW 117.6 DSD Chan 123 N44°15.17' W121°18.21' 269° 10.6 NM to fld. 4103/18E.

VOR unusable:

013°-023° byd 40 NM

034°-039° byd 40 NM

108°-119° byd 40 NM

125°-135° byd 40 NM

150°-163° byd 40 NM

188°-201° byd 40 NM blo 10,500'

188°-201° byd 69 NM

202°-219° byd 40 NM

220°-240° byd 30 NM

241°-252° byd 40 NM blo 13,000'

241°-252° byd 47 NM

253°-257° byd 40 NM

258°-268° byd 40 NM blo 10,000'

258°-268° byd 48 NM

280°-286° byd 40 NM

289°-305° byd 40 NM blo 12,500'

289°-305° byd 48 NM

326°-338° byd 40 NM

TACAN AZIMUTH unusable:

220°-240° byd 30 NM

DME unusable:

220°-240° byd 30 NM

