

WAINWRIGHT

WAINWRIGHT (AWI)(PAWI) 1 SE UTC-9(-8DT) N70°38.28' W159°59.69'

CAPE LISBURNE

H-1A, L-4I

IAP

45 B NOTAM FILE AWI

RWY 06-24: 4494X110 (GRVL) MIRL

RWY 06: REIL. PAPI(P4L)—GA 3.0° TCH 31'. Antenna.

RWY 24: REIL. PAPI(P4R)—GA 3.0° TCH 30'.

SERVICE: LGT ACTVT REIL Rwy 06 and Rwy 24, PAPI Rwy 06 and Rwy 24, MIRL Rwy 06-24—CTAF.

AIRPORT REMARKS: Unattended. Rwy cond unmt; rcmd visual insp prior to use. Rwy 06-24, 40 ft twr 500 ft N of rwy. Birds on and invof arpt. Ramp and twy sfc soft; ruts and ponding psbl. NOTE: See Notices—Drone Activity at Coastal Airport Launch Sites.

AIRPORT MANAGER: 907-852-0489

WEATHER DATA SOURCES: ASOS 132.25 (907) 763-8881. (WX CAM)

COMMUNICATIONS: CTAF 122.8

WAINWRIGHT RCO 122.5 (BARROW RADIO)


ANCHORAGE CENTER APP/DEP CON 135.3

RADIO AIDS TO NAVIGATION: NOTAM FILE BRW.

BARROW (H) (H) VORW/DME 116.2 BRW Chan 109 N71°16.41'

W156°47.29' 230° 73.8 NM to fld. 57/10E.

COMM/NAV/WEATHER REMARKS: Barrow FSS—1-800-779-7709. Local call to Barrow FSS dial 907-852-2511. For a toll free call to Fairbanks dial 1-866-248-6516.



WAINWRIGHT AS (AKØ3)(PAWT) PVT 0 N UTC-9(-8DT) N70°36.80' W159°51.62'

CAPE LISBURNE

L-4I

35 B NOTAM FILE BRW Not insp.

RWY 03-21: 3000X100 (GRVL) MIRL

RWY 03: REIL. Rgt tfc.

RWY 21: REIL.

SERVICE: LGT Bcn on consly.

AIRPORT REMARKS: CLOSED to public; Bureau of Land Management (BLM) facility. Caution: Rwy not mntnd; rcmd visual insp prior to ldg. Mult soft spots; dirt & grvl on rwy.

AIRPORT MANAGER: (907) 382-4199

COMMUNICATIONS: CTAF 126.2